

myford

ML7 LATHE

**NOTES ON
OPERATION
INSTALLATION
AND
MAINTENANCE
ALSO
PICTORIAL PARTS LIST**



**INCLUDING TRI-LEVA
SPEED SELECTOR LATHES**



ML7 LATHE

| | <i>Page</i> |
|--|-------------|
| Outline diagram | 2 |
| Safety Precautions | 2A |
| Specification | 4 |
| Standard and dismantled equipment | 5 |
| Assembly Instructions | 7 |
| Tri-Leva lathe assembly | 10a |
| Installation | 11 |
| Lubrication | 17 |
| Controls and adjustments | 21 |
| Chuck fitting | 31 |
| Instructions for ordering spares | 32 |
| Parts lists | 34 |

MYFORD ML7 3½" CENTRE LATHE




Fig. 1 Showing overall measurements for installation purposes

ATTENTION

General Safety Rules

All rotating machinery is a potential safety hazard and, therefore, care must be exercised at all times:

READ THE MANUAL CAREFULLY, especially familiarise yourself with the operation of all controls.

EARTHING. Make sure that the lathe and cabinet are electrically connected to an earthing point. If a 2-pronged connector is used an additional earthing wire should be run.

Switch 'OFF' before plugging in the connector to avoid accidental starting.

ALWAYS TURN THE SPINDLE BY HAND before switching on the motor. This will avoid damage to the bed, saddle or cross slide by swinging chuck jaws, workpiece, faceplate, bolts, etc.


CHECK THAT ALL HOLDING AND LOCKING DEVICES ARE TIGHTENED and that all keys and wrenches are clear of the moving parts of the machine.

WARNING — DANGER

This lathe has a screwed spindle nose.

Any resistance to rotation when running the spindle in reverse will unscrew a chuck, faceplate or any other attachment screwed to the spindle nose, which may result in a serious accident.

If you are unsure of the difference between forward and reverse directions, stand at the tailstock end of the lathe and view the headstock spindle along its axis. Forward rotation is achieved by an anti-clockwise movement of the spindle, whilst reverse rotation is clockwise.



During installation of the machine it is important to remove any chuck, faceplate, or any other attachment from the spindle nose, even if they were fitted to the lathe at the time of delivery. Once all electrical connections/wiring have been completed, you **MUST** check that the direction of spindle rotation is correct before any attachment is screwed to the spindle nose. Inadvertently running the machine in reverse may lead to an attachment becoming unscrewed and a serious accident could result.

When the machine is wired with a reversing switch, care should be taken to ensure that the machine is only used in reverse at **LOW SPEED UNDER NO-LOAD CONDITIONS**.

Cleaning

All bright parts are protected with rust preventative. This must be removed with white spirit or similar and machined parts should be lightly oiled before any movement of parts is attempted.

After using the machine, any swarf should be cleaned away. Wipe the bed and other exposed surfaces with an oily rag.

It should be noted that when coolant is used this may cause staining. Therefore, if coolant is used, always clean the lathe thoroughly and re-oil.

DON'TS

- Do not allow untrained or unauthorised persons to start the machine.
- Do not raise the hinged guard for access to the secondary drive belt or remove the guard for access to the primary drive until all rotation of spindle and motor has stopped.
- Do not carry out maintenance or repairs with machine still connected to electrical supply.
- Do not interfere with electrical connections whilst still connected to electrical supply.
- Do not interfere with electrical equipment unless you are qualified to do so.
- Do not attempt to stop rotating parts by hand.

DO'S

- Do have adequate space in which to work and keep it tidy – cluttered machine trays and workbenches invite accidents.
- Do have sufficient lighting available.
- Do wear safety goggles or safety shield.
- Do avoid loose apparel – wear suitable protective clothing. Loose cuffs and neckties are particularly dangerous.



Unless you are familiar with the safe techniques necessary to operate this machine, do not use it until you have sought instruction/training from an experienced person.

MACHINE SERIAL No. FOR EARLY MACHINES

In the event of queries, or orders for spares, please state the number of the machine, as shown on the rear vertical face of the rear shear of the Lathe bed, at the tailstock end of the machine, Fig. 2.




Fig. 2

MACHINE SERIAL No. FOR LATER MACHINES

In the event of queries, or orders for spares, please state the number of the machine, as shown on the front end of the bed at the left hand end of the facing for the rack, Fig. 2.




Fig. 2

Illustrations not binding in detail


MYFORD ML7 3½" CENTRE LATHE

THE MYFORD ML7 LATHE

The MYFORD ML7 Lathe illustrated is one of the most popular examples of the modern small screw cutting Lathe.

Outstanding features include the self-contained motor drive unit, and large tee-slotted boring table and the gap which allows work to be swung, which is larger than would normally clear the Lathe ways.

Note the complete guarding of the drive belts and changewheels, and the general heavy construction.



SPECIFICATION

| | | |
|--|-------------------------|--------------|
| Distance between centres | 20 inch | 32 inch |
| Swing over bed | 7 inch | |
| Swing in Gap | 10 inch | |
| Swing over boring table | 4½ inch | |
| Hole through Spindle | 19/32 inch | |
| Spindle Bored | No. 2 M.T. | |
| Spindle Speeds (six) | 35-640 or 47-870 r.p.m. | |
| Feeds (Standard finest) | .0037 in. per rev. | |
| Boring Table Travel | 5 inch | |
| Top Slide Travel | 2½ inch | |
| Leadscrew | 8 T.P.I. Acme | |
| Tailstock barrel bored | No. 2 M.T. | |
| Tailstock barrel travel | 2½ inch | |
| Overall length | 3 ft. 5 inch | 4 ft. 5 inch |
| Overall width | 2 ft. 1½ inch | |
| Nett weight (including motor) approx. | 200 lb. | 225 lb. |
| Nett weight on cabinet (incl. motor) approx. | 320 lb. | 375 lb. |
| Quick-change lathes | add = | 16 lb. |
| Tri-Leva speed selector lathes | add = | 11 lb. |

A ¼ h.p. 3 phase or ½ h.p. single phase 1420/1450 r.p.m. full load speed motor is recommended. To ensure satisfaction, a suitable motor can be supplied by the factory. State whether A.C. or D.C., exact voltage and phase.

MYFORD ML7 3½" CENTRE LATHE

STANDARD & DISMANTLED EQUIPMENT

Unpacking

Great care is taken in the packing of ML7 Lathes to ensure that the user will receive the Lathe in perfect condition, and it is important that unpacking should be carried out with the same care in order to avoid possible damage.

Shortages

Check the standard equipment supplied with the machine; as listed, and illustrated below.

All loose packing material (such as wood wool) should be set aside and thoroughly searched in the case of apparent shortages. If the missing items do not come to light, report the shortages immediately to the supplier from whom the machine was purchased.




Illustration shows ML.7 Lathe with standard equipment dismantled for packing.

L'illustration montre le tour ML7 avec équipement standard démonté en vue de l'emballage.
Die Abbildung zeigt ML7—Drehbank mit Standard-Ausrüstung, demontiert zum Verpacken.

La fotografía muestra el torno ML7 con el equipo standard preparado para su embalaje.
A ilustração mostra o Torno ML7 com o equipamento normal desmontado para ser embalado.

DISMANTLED EQUIPMENT

1. Lathe partially dismantled for packing.
2. Unit comprising countershaft arm and swing head assembly.
3. Vee cone pulley for countershaft.
4. Countershaft with locating collar.
5. 2 "Woodruff" keys (No. 606).
6. Countershaft pulley.
7. Motor platform.
8. Tie bar for motor platform.
9. Vee belt for motor drive.
10. Support stud for motor drive belt guard.
11. Motor drive belt guard.
12. Headstock belt guard.
13. Ball handle for cross-slide.

STANDARD EQUIPMENT (LOOSE)

14. 6½" dia. Faceplate.
15. Driver plate with peg.
16. Not now supplied.
17. Descriptive matter, Installation Booklet etc.
18. Oil Gun.
19. Soft and Hard Centres.
20. 3 Hexagon keys.
21. Key for Back-gear lock.
22. Motor pulley.
23. 2 Sight feed lubricators.
24. 2 Spanners.
25. 8 Changewheels. (To complete standard set of 14—6 are mounted on the machine.)

For checking only. Do not use these numbers for ordering.

MYFORD ML7 3 1/2" CENTRE LATHE

PIECES DEMONTEES—

1. Tour partiellement démonté en vue de l'emballage
2. Elément comprenant le bras de renvoi et basculeur-tendeur
3. Poulie à gradins du renvoi
4. Arbre de renvoi avec collier de blocage
5. 2 clavettes Woodruff (No. 90)
6. Poulie de renvoi (178 m/m ø)
7. Semelle pour moteur
8. Tirant de la semelle du moteur
9. Courroie trapézoïdale pour moteur
10. Goujon-support du capot de protection de la courroie moteur
11. Capot de protection de la courroie moteur
12. Capot de protection de la poupée.
13. Manivelle de commande du chariot transversal

Pour contrôle seulement — Ne pas utiliser ces chiffres pour commande.

Demontierte Ausrüstungsteile

1. Drehbank zum Teil demontiert, wie sie zum Versand kommt.
2. Antriebswippe mit Riemenspanner.
3. 3-stufige Keilriemenscheibe.
4. Vorgelegewelle mit Anschlag.
5. 2 Keilnutenkeile "Woodruff" (No. 90).
6. Keilriemenscheibe (178 mm ø) zu Vorgelegewelle.
7. Wippe zu Elektromotor.
8. Fixationsarm zu Motor-Wippe.
9. Keilriemen zu Motor-Vorgelege.
10. Tragbolzen zu Motor-Schutzhaube.
11. Schutzhaube zu Motor-Riemen.
12. Schutzhaube zu Spindelstockantrieb.
13. Winkelgriff zu Kreuzschlitten.

Diese Zahlen 1 - 25 dienen nur zur Kontrolle beim Auspacken.
Bitte beim Bestellen keinen Gebrauch dieser Nummern machen.

EQUIPO DESMONTADO

1. Torno desmontado parcialmente, listo para ser embalado.
2. Unidad que comprende el brazo del eje auxiliar y el conjunto principal oscilatorio.
3. Cono de poleas trapezoidales para el eje auxiliar.
4. Eje auxiliar con collar.
5. Dos chavetas "Woodruff" (No. 90).
6. Polsa del eje auxiliar (178 mm de diámetro).
7. Soporte del motor.
8. Tirante de sujeción del soporte del motor.
9. Correa trapezoidal.
10. Espárrago soporte para la protección de la correa del motor.
11. Protección de la correa del motor.
12. Protección de la correa del cabezal.
13. Manivela para el movimiento transversal del portaherramientas.

Para Comprobacion Solamente.
No Utilizar Estos Numeros Para Pedir Piezas.

EQUIPAMENTO DESMONTADO

1. Torno parcialmente desmontado para embalagem.
2. Unidade compreendendo o braço de contraveio e conjunto de cabeçote giratório.
3. Polie de cone em V para o contraveio.
4. Contraveio com anel para colocação.
5. 2 Chaves "Woodruff" (No. 90).
6. Roldans de contraveio (178 m/m de diámetro).
7. Base do motor.
8. Barra de fixação da base do motor.
9. Correia trapezoidal para accionamento do motor.
10. Perno de suporte para resguardo de correia de accionamento do motor.
11. Resguardo da correia de accionamento do motor.
12. Resguardo da correia do cabeçote.
13. Manipulo para a espera transversal.

Apenas Para Identificação Não Usar Estes Números Para Encomendar.

EQUIPEMENT STANDARD (libre)

14. Plateau à rainures (170 mmø)
15. Plateau pousse-toc
16. Pas fourni
17. Littérature, notice de montage etc. . .
18. Pompe à huile
19. pointes douce et dure
20. 3 clés B.T.R.
21. clé pour déblocage du harnais
22. Poulie moteur
23. 2 lubrificateurs à valve
24. 2 clés plates
25. 8 pignons (complétant le jeu standard de 14 - vis étant en place sur la machine).

Standard-Ausrüstungsteile

14. Planscheibe (170 mm Durchmesser).
15. Mitnehmerscheibe mit Stift.
16. Nicht verschafft.
17. Katalog, Aufstellungs- und Bedienungsanweisung.
18. Oelspritze.
19. Je eine harte und eine weiche Spitze.
20. Drei Inbus-Schlüssel.
21. Schlüssel zur Schaltung des Reduktionsgetriebes.
22. Motor-Keilriemenscheibe.
23. 2 Sicht-Tropfoeler.
24. 2 Doppelgabelschlüssel.
25. 8 Wechselläder (zum ganzen Standardsatz von 14 Stück gehörend, 6 montiert auf Drehbank).

EQUIPO STANDARD (INDEPENDIENTE)

14. Plato plano (170 mm de diámetro).
15. Plato para utilizar contrapunto.
16. No ahora suministrado.
17. Información de montaje y descripciones, instrucciones, etc.
18. Pistola de aceite.
19. Puntos; duro y blando.
20. 3 llaves exagonales.
21. Llave para el freno del mecanismo posterior.
22. Polea del motor.
23. 2 Lubrificadores visuales.
24. 2 llaves fijas.
25. 8 ruedas dentadas (para completar el juego "standard" de 14; seis están montadas en la máquina).

EQUIPAMENTO NORMAL (Peças soltas)

14. Prato liso de 170 m/m de diámetro.
15. Prato de transmissão com cavilha.
16. No fornecido.
17. Matéria descritiva, livrete de instalação, etc.
18. Pistola para óleo.
19. Pontos macios e rijos.
20. 3 Chaves hexagonais.
21. Chave de fixação do contraveio de mudança.
22. Polie do motor.
23. 2 lubrificadores de gota visível.
24. 2 Chaves de boca.
25. 8 rodas de muda (para completar jogo normal de 14—16 montadas no torno).

MYFORD ML7 3½" CENTRE LATHE


Cleaning

Myford machines are shipped with all parts protected by a rust preventative; all traces of this should be removed with either petrol or paraffin.

**DO NOT MOVE ANY PART OF THE MACHINE
UNTIL ALL OF THESE SURFACES HAVE BEEN
THOROUGHLY CLEANED AND OILED**

ASSEMBLY INSTRUCTIONS FOR MOTORISING EQUIPMENT

FOR LATHES FITTED WITH CLUTCH SEE ALSO PAGE 10a
FOR TRI-LEVA LATHES TURN TO PAGE 10a



ML7 Lathes have the motorising equipment and cross slide ball handle dismantled for safe and economical packing purposes, these should be assembled on the machine by the method shown in this publication.

MYFORD ML7 3½" CENTRE LATHE

The number references used throughout these assembly instructions are those shown in Figures 3 and 10.




Fig. 3

a Mount the countershaft arm/swing head assembly (1) on the back of the Lathe bed, using the three ½" dia. x 1½" long B.S.F. screws and washers which are provided. See Fig. 4. Lightly tighten the screws only at this stage.

b Check that the rubber bushes (11) are in position, slide the countershaft (2) through the left-hand bearing of the swing head, (facing the rear of the machine), and slip the headstock vee belt over the countershaft, slide the countershaft into the vee cone pulley, (3) which should be held between the swing head bearings with the small step on the left. See Fig. 5.




Fig. 5

c Pass the countershaft into the vee cone pulley until the woodruff key seat approaches the pulley bore. Insert the woodruff key into the countershaft and engage with the keyway of the cone pulley. See Fig. 6.




Fig. 4




Fig. 6

MYFORD ML7 3½" CENTRE LATHE

d Slide the countershaft right through the remaining swing head bearing; place the fibre washer on the shaft and insert the second woodruff key at the extreme end of the countershaft (right hand end). Mount the vee pulley (4), and secure with the two socket grubscrews (5). Adjust the collar (6) to allow approximately .005" end float. See Fig. 7.




Fig. 7

e Position the countershaft cone pulley opposite the headstock cone pulley and lightly tighten the two securing screws (7).

(Note: A relief is provided in the countershaft for the securing screws). To ensure correct alignment of the countershaft and headstock spindle, place a straight edge across the face of




Fig. 8

the headstock cone pulley and adjust the position of the countershaft arm assembly, so that the headstock and the countershaft cone pulleys are parallel. See Fig. 8. Finally tighten the three countershaft arm fixing screws.

f Line up the countershaft cone pulley with the headstock cone pulley using the straight edge. Finally tighten the two securing screws (7).

g Pull the belt tensioning lever forward against the stop (i.e. with the lever and knob roughly vertical) so that the cam shaft (8) is in the full lift position. Adjust the tensioning screws (9) until the slack of the belt allows approx. ½" total movement when lightly oscillated by the thumb and forefinger. This will provide an initial tension setting, which can be increased if slip is experienced when the machine is operated. See Figs. 9 and 10.




Fig. 9

h Remove the changewheel guard, assemble the motor base as shown in Fig. 11 (set as far to the right as possible), and secure by tightening the socket grubscrew in the right hand lug of the motor base.

Note: The socket grubscrew in the countershaft arm locates the assembly endwise, and should not be so tight as to prevent free swivelling of the motor base.




Fig. 10




Fig. 11

i Attach the motor base link (with flanges innermost), and secure the motor base in a horizontal position. Place the motor and lightly tighten the bolts. If the motor is not required for reversing duty, it is recommended that the correct rotation be set before mounting. Rotation should be clockwise when viewed from the pulley end. Instructions for reversing rotation are usually contained in the motor terminal box. Assemble the motor pulley on to the motor shaft. Screw in the countershaft belt guard support stud (10), until tight, and attach the countershaft belt guard. See Fig. 12.




Fig. 13

to support the weight of the motor and base before securing the motor base link. The tension can be increased if slip is experienced in operation. Replace the countershaft belt guard.

l Dismantle the two retaining plates from the headstock belt guard and slip the guard over the rubber bushes (11), on the swinghead. Replace the retaining plates.

Cross Slide Ball Handle—Assembly and Adjustment

Screw on the cross slide ball handle against the face of the feed dial, and




Fig. 12

j Slide the motor as far to the right as is possible without fouling the countershaft belt guard, but still permitting sufficient adjustment of the motor pulley on the motor shaft for the lining up of the motor and countershaft pulleys. Remove the countershaft belt guard and use the straight edge to align the motor spindle and countershaft, and also to line up the motor and countershaft pulleys. See Fig. 13. Tighten the grub screw in the motor pulley.

k Release the motor base link, place the countershaft vee belt in position and adjust the belt tension. The initial tension setting is achieved by allowing the belt

continue to wind the cross slide until the thrust shoulder of the feedscrew makes firm contact with the face of the feednut in the saddle, to prevent rotation of the feedscrew.

Hold the feed dial with a spanner and slack-off the ball handle. Adjust the feed dial to eliminate excessive end play in the feedscrew bearing, and hold with the spanner whilst the ball handle is screwed forward to lock against the feed dial. An extremely tight adjustment is not necessary since end play does not affect the accuracy of the feed.

Wind the handle in both directions to ensure that the feedscrew rotates freely.

MYFORD ML7 3½" CENTRE LATHE

ASSEMBLY INSTRUCTIONS

Lathes, fitted with a clutch

Proceed as 'a' and 'b' on page 8 noting that in this instance the countershaft is complete with actuating shaft, collar, lever assembly and lever pivot bracket.

- c Pass the countershaft through the vee cone pulley, ensuring that the flats on the shaft are lineable with the grub screws in the cone pulley, and through the second bearing. Tighten the screws in the cone pulley just sufficiently to prevent the pulley from turning on the shaft but without securing the pulley.
- d At the driving end of the shaft, place in position the thrust washer P.22, see parts list at rear of booklet, and countershaft pulley assembly including the clutch assembly, lining up the grub screws in the backplate P.14 with the dimples in the shaft P.75. Locate the backplate on the shaft by tightening one grub screw. Release and remove the sleeve nut P.7 and withdraw lever P.8 keeping adjusting collar P.2 attached to it. Tighten securely both grub screws in backplate P.14. Replace washer P.2, lever P.8 and sleeve nut P.7 and tighten nut. Adjust collar at lever end of countershaft to give .005" end float to shaft, see Fig. 7 page 9. Position lever pivot bracket on swing head with outer end flush with boss on swing head and tighten grub screws. Continue as 'e' etc. to the end on pages 9 and 10.

Tri-Leva Lathes

- a Remove changewheel guard.
- b Place the fibre washer in position on the countershaft, insert the woodruff key into the keyway and mount the vee pulley on the shaft, and secure it by means of the two grub screws.
- c Check shaft for end float. See Fig. 7 page 9. Adjust the collar if necessary.
- d Fit the motor base, etc. as described at 'h', 'i', 'j', and 'k', pages 9 and 10, including fitment of countershaft belt guard and replace the changewheel guard.
- e After removing the hexagon nut and washer S.6 and S.38 (see parts list at rear of booklet) also hexagon head screw and spherical washers S.40 and S.41, place the main frame unit over the swing head and lower it on to the front of the lower trap. Replace the hexagon nut also the spherical washers and hexagon head screw, ensuring that there is a spherical washer on each side of the support bracket S.39.

Partially lock the main frame in a position where the radial profile at the base of the main frame is approximately central with the headstock bearing caps. Position the main frame to bring the jockey pulleys in line with the belt and lock.

INSTALLATION

Foundation

It is essential that the Lathe be placed on a solid foundation. The floor material is an important consideration, concrete being the most satisfactory. If the floor is of flimsy construction, a possible solution is to cut a hole through the floor and build up a concrete foundation from the ground up to the floor level.

If the machine is to be located on an upper floor of timber construction, it should be placed directly over a beam or girder, near a wall, or at some other spot where displacement of the floor will be at a minimum.

Floor Stands

The MYFORD steel cabinet stands make ideal supports for the lathe. See Fig. 15. Wooden benches are not recommended, as they are affected by moisture and atmospheric changes. Despite the rigidity of the Lathe, a warping bench can upset the level of a Lathe in the space of a few days, and greatly impair its accuracy.




Fig. 15. Tray-top Cabinet with deep tray, raising blocks and terminal block only.

MYFORD ML7 3½" CENTRE LATHE

If the user is compelled to use a wooden bench, good dry timber must be used. The structure should be solidly built, well braced and should be securely bolted to the floor. A piece of steel sheet should be placed on the bench top to prevent the Lathe feet from sinking into the wood surface under the bolting down pressure.

The 20/024 drip tray used in conjunction with 20/025 pair of raising blocks with levelling screws will serve very well for this purpose (see Fig. 17).



Fig. 17 Drip Tray

Lathe Height

A bench height of 33-34 inches is suitable for the man of average height. Alternatively, a comfortable working height can be gauged by arranging the lathe so that the upper surface of the topslide is at elbow height.

Before bolting down, the floor stand should be packed under the feet until the top surface is roughly level.

Levelling the Lathe

If the lathe is not properly levelled, the lathe bed may be twisted, resulting in misalignment of the headstock or tailstock with the ways, causing the lathe to turn and bore taper. **ACCURATE WORK CANNOT BE EXPECTED IF THE LATHE IS NOT LEVEL.**

The precision built into a Lathe can be completely nullified by faulty, uneven mounting on bench or floor stand.

Levelling should be carried out by placing shims of thin metal or asbestos sheet jointing under the Lathe feet, the amount of packing being determined with an Engineer's precision level. Where the lathe is mounted on raising blocks having jackscrews, packing shims are not required. The level, which should be sufficiently sensitive to read .003" per foot or better, should be placed across the bed at both the headstock end and the tailstock end. See Fig. 18. After bolting down re-check for level, and make any further necessary adjustments.

Do not try to level the lathe by packing under the cabinet or bench.




Fig. 18

Illustration of bed with precision levels at two points.

MYFORD ML7 3½" CENTRE LATHE

Levelling with a Dial Test Indicator

If a precision level is not available, use a dial test indicator in the following manner, to ensure that no distortion of the lathe bed takes place when bolting down:—

Place the Lathe on the bench or floor stand with the holding down bolts loosely in position.

Grip a piece of 1" diameter material in the chuck with approximately 8" protruding, and clamp the dial indicator in the tool post with the plunger located at the extreme end of the test bar as shown in Fig. 19.




Fig. 19

Showing test piece in chuck and dial indicator in tool clamp.

Rotate the headstock spindle by hand, and adjust the dial indicator, so that the zero mark lies midway between the extremes of the pointer movement.

So long as the lathe bed is not strained the dial indicator will continue to register zero when holding down bolts are tightened but any distortion due to bolting down on to an uneven surface will be shown immediately by the dial indicator.

The lathe feet should be shimmed, so that, when the holding down bolts are finally tight, the dial indicator still reads zero.

Checking the Levelling

A final check of the levelling can be carried out by turning a test piece as shown in Fig. 20. The test piece should be approximately 1" dia. by 4" to 6" long and should be relieved in the middle so as to leave about ½" for test turning at each end.

Take a very light finishing cut, (.002") across both collars without the use of the tailstock and without alteration of the tool setting. Measure the dia. of each collar with a micrometer. The collars should be the same dia., if not the same, a further adjustment of the packing is required.

If the dia. of the test piece is larger at the free end, packing should be increased under the FRONT of the foot at the tailstock end, or under the BACK of the foot if smaller.




Fig. 20

Showing test piece with two collars

Readjustment

It may be necessary to readjust the packing shims from time to time, especially if the lathe is mounted on a wooden floor or bench.

Electric Motors and Switch Wiring (not applicable for two speed Tri-leve lathes)

The lathe is designed for use with a 1425 r.p.m., 50 Hz or 1750 r.p.m., 60 Hz motor. For three phase supply this should be ½ h.p. For single phase on the ML7, ¾ h.p. is required to provide the necessary starting and pull out torque. Suitable motors, with a choice of switch control gear, are available.

Primary belt tension is obtained by moving the motor up or down on the countershaft arm, which is drilled for the mounting of motors which have slotted feet.

It is also provided with slots so that motors in IEC frame 71, having holes in the feet, can be readily accommodated. Any other motor having holes in the feet must be mounted on steel strips with studs, suitably disposed so as to pass through slots in the countershaft arm.

There are two basic types of switch control gear. The first, which is best suited to the home user, is a rotary reversing switch. This incorporates no-volt release which, in the event of a power break, will automatically return to the 'off' position. They are suitable for bench mounted lathes and lathes fitted to tray top cabinet stands. The switch comes complete with switch to motor wiring harness, a gland ready fitted to take customers' supply cable and a packing block which allows for either bench or cabinet mounting.

The second type of switch control gear – the complete safety switch package – is essential for both Industrial and Educational installations. This comprises: a lockable isolator switch, reversing push button starter with no-volt and overload release protection, mushroom head stop button operating on 110 volt control circuit, and a 12 volt tapping for a safe worklight. The package comes complete with switch to motor wiring harness, a gland ready fitted to take customers' supply cable and a packing block which allows for either bench or cabinet mounting.

Single phase motors, purchased independently, but intended for reversing with our switch control gear, must have four terminals for the separate connections to the starting and running windings. Any bridge pieces connecting starting to running windings must be removed before connecting motor to reversing switch.

MYFORD ML7 3½" CENTRE LATHE

Complete electrical switch package




Fig. 4 Single Phase




Fig. 4a Three Phase

| MOTOR | STARTING WINDING | RUNNING WINDING | RUNNING WINDING | STARTING WINDING |
|------------------|------------------|-----------------|-----------------|------------------|
| CROMPTON | Z | A | A2 | T |
| AEI | A1 | T2 | T3 | A2 |
| ENGLISH ELECTRIC | 1 | 2 | 3 | 4 |
| BROOK | Z1 | A1 | A2 | Z2 |

Terminal markings of alternative makes of motors
Fig. 5

Earthing It is important to make sure that the stand and the Lathe are electrically connected to a satisfactory earthing point. Should any difficulty be found in wiring and running the motor the advice of an electrician, who is experienced in motor wiring, should be sought.

LUBRICATION

After installing the Lathe, refer to the lubrication charts on Pages 19 and 20 and treat all points with the recommended lubricants. An oil gun is supplied for use with the pressure nipples fitted to each machine. Careful attention should be paid to the lubrication of the headstock bearings during the first few hours of running.

Headstock Bearings

The ML.7 headstock bearings are lubricated from sight feed lubricators, Fig. 28. Feed is controlled by a needle valve which is adjusted by the thumb screw nut at the top of the lubricator, the oil drip being visible through a sight glass below the valve.

Normally the drip should be set as slow as possible but if prolonged high speed is undertaken the rate may be increased.

The lubricator is filled by inserting an oil can spout into one of the filler caps on the oil reservoir.

SIGHT FEED LUBRICATOR




Fig. 28

1. LOCKING NUT
2. RESERVOIR
3. STAND PIPE
4. CORK SEALING WASHER
5. CHAMBER BUSH
6. SIGHT CHAMBER
7. NEEDLE VALVE ASSEMBLY
8. FILLER CAP
9. SPRING
10. OIL FILTER
11. RESERVOIR BASE
12. SIGHT GLASS

IMPORTANT: WHENEVER THE HEADSTOCK REDUCTION GEAR IS USED, ENSURE THAT THE HEADSTOCK PULLEY BEARING IS WELL LUBRICATED VIA THE OIL NIPPLE AT THE LARGE END OF THE PULLEY. Fig. 29.




Fig. 29. Showing the oil nipple for headstock pulley bearing lubrication

General

Daily cleaning and correct lubrication of the machine will greatly increase its working life. Excess oil should be wiped from oiling points, as oil and dirt form an abrasive compound which can easily damage precision bearing surfaces.

Wipe the bed and other sliding surfaces with a clean oily rag at frequent intervals. Use a brush to clean spindle nose threads, gear teeth, leadscrew threads etc.

At regular intervals, the leadscrew should be thoroughly cleaned with a stiff brush and paraffin, and oiled freely along its entire length.

Keep the lathe completely covered between working periods. The MYFORD waterproof Lathe cover shown in Fig. 30 will provide excellent protection from moisture and abrasive dust when the Lathe is not in use.





Fig. 30. Lathe cover.



LUBRICATION CHART. Use 80024 Esso Nuto H32 except where otherwise stated (Under I.S.O. VG32)

AT REGULAR INTERVALS

1. **Countershaft.** Use the oil gun on both nipples.
2. **Headstock Spindle.** Check the oil level of Sight Feed Lubricator. Lubricate with oil.
3. **Headstock Pulley.** Lubricate with oil frequently whenever the reduction gear is used via the oil nipple at the large end of the pulley.
4. **Backgears and Change-gear teeth.** A small amount of 80025 Esso Febis K68 will effectively lubricate.
5. **Change-wheel Stud.** Oil frequently.
6. **Turnbler Gears.** These fast running components should be frequently lubricated whenever the gears are being used.
7. **Backgear Spindle.** Use the oil gun frequently, whenever the reduction gear is used.

8. **Apron Reservoir.** Use the oil gun. This supply is distributed to the hand-wheel and rack pinion shafts and also feeds the reduction gear.
9. **Saddle.** Use the oil gun on both nipples; one over each of the two bearings, one at the rear.
10. **Topslide Ways.** Clean and apply 80025 Esso Febis K68.
11. **Cross-slide Ways.** Clean and apply 80025 Esso Febis K68.
12. **Cross-slide Ways.** Clean and apply 80025 Esso Febis K68.
13. **Tailstock Barrel.** Use the oil gun on nipple shown.

14. **Lead-screw.** Clean with a stiff brush and apply 80025 Esso Febis K68.
15. **Rack.** Apply 80025 Esso Febis K68.
16. **Cross-slide and Topslide Feed-screws.** Oil occasionally from underneath using 80025 Esso Febis K68.
17. **Apron supply and recommend Esso Nuto H32 Oil for other territories where it is available.**


NOTE. For starred items Nos. 5, 7, 15, 16, 17, Royal MTS 1000 or Castrol M53 grease should be used in those territories where it is available.

N.B. The frequency of lubrication given above is intended as a guide only. Under certain conditions, e.g. continuous use for long periods, or where the counter-shaft, lead-screw bearings, change-wheel studs, etc. will require more frequent lubrication.

14. **Swing Head Pin and Eccentric.** Apply 80025 Esso Febis K68.
15. **Lead-screw Bearings.** Use the oil gun on both nipples.

OCCASIONALLY

16. **Swing Head Pin and Eccentric.** Apply 80025 Esso Febis K68.
17. **Lead-screw Bearings.** Use the oil gun on both nipples.



MYFORD ML7 3½" CENTRE LATHE

CONTROLS & ADJUSTMENTS

DO NOT OPERATE THE LATHE until all of the following instructions have been carefully read and the controls and adjustments are fully understood.




Fig. 31 Showing the main parts of the lathe.

(Fitted 1466 Countershaft Clutch)

- | | |
|--------------------------------|-----------------|
| (1) COUNTERSHAFT | (7) SADDLE |
| (2) ELECTRIC MOTOR | (8) CROSS SLIDE |
| (3) HEADSTOCK | (9) TOPSLIDE |
| (4) LEADSCREW DRIVE GEAR TRAIN | (10) TOOLPOST |
| (5) LEADSCREW | (11) TAILSTOCK |
| (6) APRON | |

MYFORD ML7 3½" CENTRE LATHE

Headstock Spindle Drive

A compact motorising unit which makes the ML.7 completely self contained, is attached to the rear of the lathe bed. The motor is mounted on a swinging platform and the drive is conducted by vee belt from the motor to a countershaft. The vee cone pulleys on the countershaft and headstock spindle give a range of three speeds which is extended to six by the provision of a 6 - 1 reduction gear on the headstock spindle. Fig. 32.




Fig. 32

| HEADSTOCK SPINDLE SPEEDS. | | | | |
|---|-------------------------------------|-----------|--------------------------|-----------|
| (1420/1450 R.P.M. FULL LOAD SPEED MOTOR) | | | | |
| SPINDLE SPEEDS WITH 1750 R.P.M. (60 CYCLE A.C.) MOTOR IN BRACKETS | | | | |
| Headstock Belt Position | 1 7/8" Dia. Motor Pulley (Standard) | | 2 1/2" Dia. Motor Pulley | |
| | Ungearred | Gearred | Ungearred | Gearred |
| 1 | 200 (246) | 35 (43) | 273 (338) | 47 (58) |
| 2 | 357 (438) | 62 (76) | 487 (600) | 84 (103) |
| 3 | 640 (785) | 110 (135) | 870 (1070) | 152 (187) |

MYFORD ML7 3½" CENTRE LATHE

Speed Changing

Access to the headstock belt for speed changing is attained by sliding up the front guard, as shown in Fig. 33 and the headstock belt tension is released by the operation of the belt tensioning lever.

DO NOT ATTEMPT TO CHANGE THE HEADSTOCK BELT POSITION WHILST THE LATHE IS RUNNING, OR WITHOUT OPERATING THE BELT TENSIONING LEVER

The coupling of the pulley to the spindle for direct or ungeared driving is achieved by a sliding key which engages with the headstock pulley sleeve gear. The sliding key is locked in position by means of a cap head screw, which is released to withdraw the key whenever the geared speeds are required.

To operate the reduction gear, withdraw the sliding key and shift the back gear operating lever to the upper position.




Fig. 33. Location of the Headstock Controls.

- (1) BELT TENSION RELEASE LEVER (3) BACK GEAR LEVER
(2) SCREW FOR BACK GEAR KEY (4) TUMBLER REVERSE LEVER

DO NOT ATTEMPT TO ENGAGE THE REDUCTION GEARS WHILST THE SPINDLE IS REVOLVING

MYFORD ML7 3½" CENTRE LATHE

Headstock Bearings

The headstock is fitted with Glacier T.1 Alloy anti-friction bearings. Top and bottom bearing halves are fitted accurately in the bearing housing and form a solid support against spindle journal loads. Every care is taken to ensure correct bearing adjustment before the machine leaves the Works, and bearings should not be interfered with unless necessary. For the purpose of bearing adjustment, a pad comprised of brass shims is fitted between the two housing faces. This shim pad has a solid appearance but is made of .002" laminations, and by inserting a penknife blade it is an easy matter to peel off the desired thickness to allow the bearings closer contact with the spindle. After removing a .002" shim it will be necessary to scrape or file some proportional amount from the bearing half contact faces, giving a good seating to bearing halves and housing cap; in effect a solid condition with running clearance only between spindle and bearing. Whenever bearings need adjustment use marking blue for contact check, carefully scraping any high spots with a half round bearing scraper.

Spindle end thrust adjustment is made by the screwed collar at the end of the Spindle, and care should be taken to ensure the elimination of end float without undue friction by over tightening.




Fig. 34—Showing Method of Adjusting ML7 Lathe Headstock Bearings.

Replacement of Headstock Vee Belt

The vee rope can readily be replaced when necessary by removing the bearing caps and lifting out the spindle assembly as a complete unit; care should be taken to ensure that the shims are replaced in the same positions and that the caps are locked up tight after replacement.

Replacement of Headstock Vee-Belt—Tri-Leva Lathes

a Remove the main frame unit; see assembly instructions, 'e', page 10a.

b Remove cheesehead screw and washer S.60 and S.61 which fasten link S.59 (see parts list at end of booklet) to upper belt trap. Unscrew caphead screws S.10 which hold clamps S.9 and S.11 to upper belt trap S.8. The clamps and belt trap may now be removed.

c Dismantle headstock spindle and countershaft as for basic machine.

N.B. When replacing upper belt trap do not over tighten screws S.10 which secure the clamps. The upper trap should be free to move by normal hand pressure. The slotted link S.59 is left free until, with the screws tightened as above, the trap has been positioned to give approximately ½ inch clearance between the inner face of the trap and the outer face of the belt. When the trap has been positioned replace screw and washer S.9 and S.11 and tighten.

TUMBLER REVERSE

The Tumbler Reverse or Leadscrew Reverse gear, provides a quick means of changing the rotation of the leadscrew drive to reverse the direction of travel of the lathe carriage. The central lever position is neutral and disengages the leadscrew drive.

**DO NOT MOVE THE TUMBLER REVERSE LEVER
WHILST THE SPINDLE IS REVOLVING**

POWER CARRIAGE FEEDS

Standard change gear lathes are equipped with a set of 14 change wheels for cutting various screw threads and obtaining various power longitudinal feeds.

To set up the lathe for threading or feeding, refer to the change wheel chart inside the change wheel guard Figs. 37 and 38.

The thread pitch, or feed, to be set up will be located in the first two columns under the headings T.P.I. and Feed per Rev., respectively. In the third column under the heading DRIVER is listed a number of teeth in the change wheel which should be placed on the tumbler reverse stud.




Fig. 35. Showing Leadscrew Drive.

- | | |
|---------------------------|--------------------|
| (1) TUMBLER REVERSE LEVER | (5) 1st STUD GEARS |
| (2) TUMBLER REVERSE GEARS | (6) 2nd STUD GEARS |
| (3) 25T SPINDLE GEAR | (7) LEADSCREW GEAR |
| (4) TUMBLER CLUSTER GEAR | (8) SPACER |

MYFORD ML7 3½" CENTRE LATHE

In the fourth and fifth columns under 1st stud and 2nd stud are shown the gears or pairs of gears which should be placed on the 1st and 2nd studs respectively.

The 6th column lists the gear to be placed on the leadscrew under the heading LEADSCREW.

The column headed SET-UP refers to the number of the diagram, Fig. 36, which will indicate the arrangement of gears and spacers for the pitch in question, see also Fig. 35 which shows set-up as in Diagram 3, Fig. 36.

When setting up the gear train sufficient backlash between each pair of meshing gears should be allowed. When the lathe is in operation the play in the gears is automatically taken up according to the direction of travel; the amount of gear clearance does not influence the accuracy of thread cutting. Gear noise can be reduced by the application of grease, preferably graphited.




Fig. 36

MYFORD ML7 3 1/2" CENTRE LATHE

INCH PITCHES

| T P I | FEED PER REV | DRIVER | 1 ST STUD | | 2 ND STUD | | LEAD SCREW | SET - UP |
|-------|--------------|--------|----------------------|----------|----------------------|----------|------------|----------|
| | | | DRIVEN | DRIVER | DRIVEN | DRIVER | | |
| .8 | .250 | 20 | IDLE | 75 WHEEL | | | 20 | 1 |
| 9 | .111 | 40 | IDLE | 60 WHEEL | | | 45 | 1 |
| 10 | 1.000 | 40 | IDLE | 60 WHEEL | | | 50 | 1 |
| 1 | 0.909 | 40 | IDLE | 60 WHEEL | | | 55 | 1 |
| 2 | 0.833 | 40 | IDLE | 50 WHEEL | | | 60 | 1 |
| 4 | 0.714 | 20 | IDLE | 70 WHEEL | | | 35 | 1 |
| 6 | 0.625 | 20 | IDLE | 70 WHEEL | | | 40 | 1 |
| 8 | 0.556 | 20 | IDLE | 70 WHEEL | | | 45 | 1 |
| 9 | 0.526 | 40 | 3B | 20 | IDLE | 55 WHEEL | 50 | 2 |
| 20 | 0.500 | 20 | IDLE | 70 WHEEL | | | 50 | 1 |
| 22 | 0.455 | 20 | IDLE | 70 WHEEL | | | 55 | 1 |
| 24 | 0.417 | 20 | IDLE | 70 WHEEL | | | 60 | 1 |
| 25 | 0.400 | 40 | 50 | 30 | IDLE | 45 WHEEL | 75 | 2 |
| 26 | 0.385 | 20 | IDLE | 70 WHEEL | | | 65 | 1 |
| 28 | 0.357 | 30 | 35 | 20 | IDLE | 50 WHEEL | 60 | 2 |
| 32 | 0.313 | 30 | 40 | 20 | IDLE | 55 WHEEL | 60 | 2 |
| 36 | 0.278 | 30 | 45 | 20 | IDLE | 55 WHEEL | 60 | 2 |
| 40 | 0.250 | 30 | 50 | 20 | IDLE | 55 WHEEL | 60 | 2 |
| 44 | 0.227 | 20 | 55 | 30 | IDLE | 50 WHEEL | 60 | 2 |
| 46 | 0.217 | 20 | 46* | 30 | IDLE | 45 WHEEL | 75 | 2 |
| 48 | 0.208 | 20 | 60 | 35 | IDLE | 45 WHEEL | 70 | 2 |
| 52 | 0.192 | 20 | 50 | 25 | IDLE | 55 WHEEL | 65 | 2 |
| 54 | 0.185 | 20 | 45 | 20 | IDLE | 55 WHEEL | 60 | 2 |
| 60 | 0.167 | 20 | 50 | 25 | IDLE | 55 WHEEL | 75 | 2 |
| 64 | 0.156 | 35 | 40 | 20 | 60 | 30 | 70 | 3 |
| 72 | 0.139 | 25 | 50 | 30 | 45 | 20 | 60 | 3 |
| 80 | 0.25 | 25 | 50 | 35 | 70 | 30 | 75 | 3 |
| 88 | 0.114 | 30 | 40 | 25 | 55 | 20 | 75 | 3 |
| 92 | 0.109 | 20 | 46* | 30 | 50 | 20 | 60 | 3 |
| 96 | 0.104 | 30 | 40 | 20 | 60 | 25 | 75 | 3 |
| 104 | 0.096 | 20 | 50 | 30 | 60 | 25 | 65 | 3 |
| | 0.087 | 20 | 55 | 30 | 60 | 25 | 65 | 3 |
| 112 | 0.089 | 25 | 50 | 30 | 60 | 20 | 70 | 3 |
| 120 | 0.083 | 20 | 50 | 30 | 60 | 25 | 75 | 3 |
| | 0.058 | 20 | 55 | 25 | 60 | 20 | 65 | 3 |
| | 0.043 | 20 | 60 | 25 | 65 | 20 | 75 | 3 |
| | 0.037 | 20 | 65 | 25 | 70 | 20 | 75 | 3 |
| | 0.018 | 12* | 65 | 20 | 70 | 20 | 75 | 3 |

LEADSCREW 8 THREADS PER INCH

● Not a standard Gear. Available as an extra.

* 12/25 tooth Tumbler Cluster Gear (1974) available as an extra.

Fig. 37

METRIC PITCHES

| FEED PER REV MILLIMETERS | DRIVER | 1 ST STUD | | 2 ND STUD | | LEAD SCREW | SET - UP |
|-----------------------------|--------|----------------------|--------|----------------------|----------|------------|----------|
| | | DRIVEN | DRIVER | DRIVEN | DRIVER | | |
| 0.20 | 21* | 50 | 30 | 60 | 21* | 70 | 3 |
| 0.25 | 30 | 40 | 21 | 60 | 21 | 70 | 3 |
| 0.30 | 21 | 60 | 45 | 50 | 21 | 70 | 3 |
| 0.35 | 35 | 40 | 21 | 50 | 21 | 70 | 3 |
| 0.40 | 21 | 50 | 21 | IDLE | 60 WHEEL | 70 | 2 |
| 0.45 | 46 | 40 | 21 | 50 | 21 | 70 | 3 |
| 0.50 | 21 | 50 | 45 | 40 | 20 | 60 | 3 |
| 0.60 | 21 | 50 | 45 | 40 | 30 | 75 | 3 |
| 0.70 | 21 | 50 | 21 | IDLE | 60 WHEEL | 40 | 2 |
| 0.75 | 45 | 40 | 35 | 50 | 21 | 70 | 3 |
| 0.80 | 21 | 50 | 45 | IDLE | 40 WHEEL | 75 | 2 |
| 0.90 | 45 | 25 | 21 | 40 | 21 | 70 | 3 |
| 1.00 | 45 | 40 | 21 | IDLE | 50 WHEEL | 75 | 2 |
| 1.10 | 45 | 50 | 55 | 40 | 21 | 75 | 3 |
| 1.20 | 45 | 25 | 30 | 50 | 21 | 60 | 3 |
| 1.25 | 45 | 40 | 21 | IDLE | 50 WHEEL | 60 | 2 |
| 1.30 | 65 | 25 | 21 | 40 | 21 | 70 | 3 |
| 1.40 | 45 | 25 | 35 | 50 | 21 | 60 | 3 |
| 1.50 | 21 | 50 | 45 | IDLE | 35 WHEEL | 40 | 2 |
| 1.60 | 45 | 25 | 21 | IDLE | 55 WHEEL | 75 | 2 |
| 1.75 | 45 | 20 | 35 | 50 | 21 | 60 | 3 |
| 1.80 | 30 | 40 | 45 | 25 | 21 | 50 | 3 |
| 2.00 | 60 | 40 | 21 | IDLE | 55 WHEEL | 50 | 2 |
| 2.25 | 45 | 40 | 60 | 40* | 21 | 50 | 3 |
| 2.50 | 45 | 30 | 21 | IDLE | 50 WHEEL | 40 | 2 |
| 2.75 | 55 | 20 | 30 | 40 | 21 | 50 | 3 |
| 3.00 | 45 | 25 | 21 | IDLE | 60 WHEEL | 40 | 2 |
| 3.50 | 60 | 20 | 35 | 40 | 21 | 50 | 3 |

The tumbler reverse lever should not be shifted during thread cutting operations, as such movement may alter the position of the headstock spindle relative to the lead-screw, thereby causing split threads.

Fig. 38

MYFORD ML7 3½" CENTRE LATHE




Fig. 39—Thread Dial Indicator Mounting for ML7 Lathe

Thread Dial Indicator

Every lathe is provided with a machined facing on the right hand side of the saddle, drilled and tapped ready to receive this unit. Provision is made for the alignment of the dial markings with the zero mark on the indicator body as shown in Fig. 39. The indicator can be readily engaged or disengaged, and operates as follows:—

- (1) For even number threads the clasp nut can be engaged at any numbered mark on the dial.
- (2) Odd number threads should always be engaged at the same number or any alternate number.
- (3) For half threads per inch, always engage the same number.
- (4) For other threads, m/m sizes, etc., it is recommended that the clasp nut should not be disengaged.

Note. Threads that are exact multiples of the leadscrew pitch (8 T.P.I.) do not require the use of an indicator.

Carriage Controls

Fig. 40, gives the names and positions of the carriage controls. The apron handwheel moves the carriage along the bed, and the cross slide and top slide ball handles move the toolpost in and out.

Both cross slide and top slide feedscrew dial graduations represent slide movement in increments of .001".




Fig. 40. Showing the carriage controls.

- | | |
|-----------------------------|---------------------------|
| (1) CROSS SLIDE BALL HANDLE | (5) TOP SLIDE BALL HANDLE |
| (2) SWIVEL GRADUATIONS | (6) SADDLE CLAMP |
| (3) LOCKING POST | (7) MICROMETER DIALS |
| (4) TOOL POST | (8) APRON HANDWHEEL |
| (9) HALF NUT LEVER | |

MYFORD ML7 3½" CENTRE LATHE

A clamp screw is provided on the saddle to lock the carriage to the bed for facing, parting off, and milling etc., CARE SHOULD BE TAKEN TO SEE THAT THE CLAMP SCREW IS NOT TIGHTENED WHEN THE CARRIAGE IS TRAVERSED BY THE LEADSCREW.

Longitudinal Feed

Depress the half-nut lever to engage the half nuts with the leadscrew when longitudinal movement of the carriage is required.

If the half-nuts do not engage immediately, DO NOT USE FORCE. Wait until the leadscrew rotates to a position which permits engagement of the half-nuts by gentle pressure only.

The thread dial indicator will give visual guidance and show when the leadscrew is in the correct position for nut engagement.

Saddle and Slide Rests

All slides are provided with normal gib adjustment, and steel plates are fitted beneath the saddle to prevent saddle lift. These plates bear on the underside of the lathe bed and adjustment to ensure close contact is by means of laminated shims similar to those used for the headstock bearings. The same procedure is adopted when adjustment becomes necessary.

The saddle and compound slides on a centre lathe are designed to withstand the cutting force of the tool and it is therefore necessary to maintain, by periodic adjustment, the close contact of gib strip and slide surface. Careful attention should be given to the screw adjustment to ensure an even pressure of the gib strip.

When stripping the compound slides for thorough cleaning and lubrication re-adjust the slides without feed screws and screw support brackets, testing the slides by hand motion, re-assembling the feed screw units as the last operation. By the very fact that the slides are built upon each other deflection of the turning tool is transmitted through the slides; so it is important to see that your lathe tool has the minimum overhang and is flat on its clamping surface.

Saddle Gib Strip Adjustment

When adjusting the saddle gib strip, first adjust the two outer screws, ensuring equal pressure. After tightening the locknuts, check for freedom of movement but without play. Next, adjust the inner screws, so that they contact the strip without increasing the friction and tighten their locknuts.

Apron

The apron is anchored to the saddle by means of four socket head screws, and a periodic check should be made to ensure that these screws are tight.

The 2 B.A. x 1½" cap screw (parts list, L14) must be so adjusted that the leadscrew nut will not close sufficiently to cause it to bind on the leadscrew.

The Tailstock

The Tailstock is securely locked to the bed by the quick-acting clamp lever which is located at the rear of the tailstock, Fig. 41.

The barrel is locked in place by means of the thumb lever, also at rear.

The Tailstock can be set-over $\frac{7}{16}$ " for taper turning, by first loosening the bed clamp and then adjusting the screws which are located in the tailstock body, directly above the base tenon. A zero mark is engraved at the end of the tailstock to serve as a rough guide to set-over amounts, and to assist in returning the tailstock to its normal position for parallel turning.

Tailstock Gib Adjustment

Release gib securing screws and retighten until just nipped.

Adjust thrust screws just sufficiently to remove all trace of play of the tailstock relative to the bed shears, but without causing undue friction.

Retighten gib securing screws and check for freedom of movement but lack of "play".

MYFORD ML7 3½" CENTRE LATHE




Fig. 41. Rear view of the tailstock.

- | | |
|--------------------|-------------------------|
| (1) CLAMP LEVER | (4) GIB THRUST SCREWS |
| (2) THUMB LEVER | (5) GIB SECURING SCREWS |
| (3) SET OVER SCREW | |

Tri-Leva Speed Selector

Belt tension is covered in two ways. All three belts may be adjusted simultaneously by means of the adjusting screws on the cam shaft (as for the basic machine). These should be adjusted to bring the swing head in a position approximately in the centre of the main frame clearance aperture. For individual belt adjustment remove the four screws securing the front plate and detach the plate; see left hand illustration below. The adjusting screws (1) are slotted so that they remain locked in the set position.

To adjust, push the pulley supporting arm (2) inwards to clear the adjusting screw (1), to enable the latter to be turned. The belts should be tensioned to such a degree that there is no feeling of force when the lever is depressed into the operating position.

Trip Adjustment. If an engaged lever is not tripped when a further lever is depressed, the trip plate setting may be varied by raising or lowering the pivot arms (1); see right hand illustration below. Partially release the socket set screw (4) and release locknuts (3). Alter the setting of the stop screws, testing the trip before finally locking the locknuts and the socket set screw (4).




Fig. 41a




Fig. 41b

CHUCK FITTING

- (1) Before screwing backplate on to spindle nose, ensure the cleanliness of spindle nose, backplate register, faces and thread.
- (2) Screw backplate firmly on spindle nose.
- (3) Machine register diameter to light tap fit in chuck body.




Fig. 42

Note. With three-jaw gear scroll chucks, contact is made with the outer face of the chuck body and clearance with the inner face, see Fig. 42.

With four-jaw independent chucks, contact is made with the inner face of the chuck body, see Fig. 43.

With 6" four-jaw independent chucks contact is also made with the inner face of the chuck body but the threaded portion of the backplate is housed in the chuck body to eliminate chuck overhang, see Fig. 44.




Fig. 43

- (4) Remove backplate from spindle nose. Mark out and drill clearance holes for three-jaw chuck locking bolts, and core diameter tapping holes for four-jaw chuck locking bolts. Remove all burrs with counter-sink or scraper. Care should be taken when marking out the holes to ensure clearance between the bore of the hole and bolt stem. With the four-jaw chuck backplate, the drilling centres can easily be marked by means of a centre punch with the shank diameter acting as a guide through the chuck body holes. After centring one hole, drill, tap and lock the backplate lightly with a locking bolt. The other three holes can then be centred without fear of the backplate shifting.
- (5) When tightening locking bolts, apply pressure evenly and gradually to all four in rotation.




Fig. 44

CHUCK BACKPLATES & THREADED BODY CHUCKS

Register bores are held to very close limits. When backplates or threaded body chucks are supplied as separate units after the machine has left these works the register bore may need very light scraping or polishing with fine emery cloth.

Do not screw equipment on to the spindle nose without ensuring that the spindle register diameter is lightly smeared with fine oil.

INSTRUCTIONS FOR ORDERING REPLACEMENT PARTS

The following information should be supplied with the order:—

1. Type and Serial Number of the lathe, and in the case of lathes with gearboxes fitted, also the serial number of the gearbox. For location of numbers see Figs. 45 and 46.
2. Section letter and item number of part as listed.
3. Quantity Required.




Fig. 45




Fig. 46

As it is the Company's policy to improve its products whenever opportunity occurs, designs are liable to modification at any time. In some cases, due to the nature of the part, it will be necessary for us to supply additional related parts, particularly if the item required has been altered.

MYFORD ML7 3 1/2" CENTRE LATHE


INSTRUCTIONS POUR LES COMMANDES DE PIÈCES DE RECHANGE

Les indications ci-après sont à fournir avec la commande:

1. Type et numéro de série du tour, et, pour les tours équipés de boîtes de vitesses, également le numéro de série de cette boîte.
Pour l'emplacement de ces nombres, voir fig. 45 et 46.
2. La lettre de la section de classification ainsi que le numéro de référence de la pièce, extrait du tableau.
3. Quantité désirée.

La politique de la Société visant toujours à l'amélioration des pièces chaque fois que l'occasion s'en présente, les dessins sont susceptibles de subir des modifications à tout instant. Dans certains cas, et en raison de la nature de la pièce, il sera nécessaire que nous fournissions des pièces supplémentaires, notamment si la pièce demandée a subi des modifications.

SERIAL NUMBER



SERIAL NUMBER




Fig. 45

INSTRUKTION FÜR DAS BESTELLEN VON ERSATZTEILEN

Eine Bestellung über Ersatzteile soll folgende Angaben enthalten:

1. Typ und Serien-Nummer der Drehbank, und in denjenigen Fällen wo die Drehbänke bereits mit Schnellwechselladungen ausgestattet sind, auch die Serien-Nummern derselben.
Wie die Nummern zu finden sind, zeigen Abb. 45 und 46.
2. Buchstabe der Schnittzeichnung und die in der Liste eingetragene Nummer des Ersatzteils.
3. Benötigte Anzahl.


Da das MYFORD-Werk jede Gelegenheit ergreift seine Produkte den neuesten Anforderungen der Technik anzupassen, unterliegen die Zeichnungen stetigen Änderungen. Je nach der Art des Stückes kann es in speziellen Fällen unumgänglich sein, dass zusätzliche, ähnliche Ersatzteile geliefert werden müssen, besonders dann, wenn das verlangte Stück geändert wurde.

INSTRUCCIONES PARA PEDIR PIEZAS DE REPUESTO

La información siguiente debe acompañar al pedido:

1. Tipo y número de serie del torno, y en el caso de torno dotado de caja de cambios, incluir también el número de la misma.
Para localizar los números véanse las figuras 45 y 46.
2. Letra de la sección correspondiente del diagrama y número de referencia de la pieza, según está clasificada.
3. Cantidad requerida.

Como es norma de la Compañía el mejorar sus productos en toda ocasión que se requiera, el diseño está sujeto a modificaciones en cualquier momento. En algunos casos, debido a la naturaleza de la pieza, será necesario que suministremos partes anexas adicionales particularmente si la pieza ha sido modificada.



SERIAL NUMBER

Fig. 46


INSTRUCCOES PARA ENCOMENDAR PECAS DE SUBSTITUICAO

Com a encomenda devem ser dadas as seguintes informações:

1. Tipo e número de série do Torno, e, em casos de tornos com caixa de velocidades adaptada, indicar também o número de série da caixa de velocidades.
Para encontrar os números ver as figuras 45 e 46.
2. Letra do corte esquemático e número de ordem da peça conforme relação.
3. Quantidade necessária.

Como é norma da Firma melhorar os seus productos sempre que se proporcione ocasião, os desenhos estão sujeitos a modificação em qualquer altura. Em alguns casos, devido à natureza da peça, ser-nos-á necessário fornecer peças adicionais, especialmente se o artigo requerido tiver sido modificado.

A



BED, LEADSCREW AND GEAR TRAIN ASSEMBLY

SECTION A
BED, LEADSCREW and GEAR TRAIN
ASSEMBLY

| Drg. Ref. | Part No. | Description | No. Off/Mc. | Drg. Ref. | Part No. | Description | No. Off/Mc. |
|-----------|-----------|---|-------------|-----------|-----------|---|-------------|
| A3 | 65000 | Oil Nipple (2 B.A.) | 2 | A37 | 70/11326 | Stud | 1 |
| A5 | 70/1113 | Distance Collar | 1 | A38 | 100309 | Hexagon Head Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 3 |
| A6 | 100308 | 'Simmonds' Nut ($\frac{1}{8}$ " B.S.F.) | 1 | A39 | A4725 | Stud | 2 |
| A7 | 70/1114 | Pin | 4 | A40 | 70/1134/1 | L.H. Leadscrew Bracket Assembly | 1 |
| A8 | 100307 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{2}$ ") | 2 | A41 | 70/1105/2 | Change Gear Guard Backplate | 1 |
| A11 | A2137 | Thrust Screw | 1 | A42 | A4736 | Change Gear Quadrant Assembly | 1 |
| A12 | 70/1112/1 | Rack | 6 | A43 | 70002 | Woodruff Key No. 404 | 2 |
| A13 | 100026 | Cap Screw (2 B.A. x $\frac{1}{2}$) | 1 | A44 | 70005 | Washer ($\frac{1}{8}$ ") | 2 |
| A16 | 70/1106/2 | Change Gear Guard | 1 | A45 | 100057 | Hexagon Nut ($\frac{1}{8}$ " B.S.F.) | 2 |
| A17 | A2639 | Screwcutting Chart | 1 | A46 | 100018 | Cheese Head Screw (2 B.A. x $\frac{1}{2}$ ") | 2 |
| A18 | 100241 | Rivets (No. 0 x $\frac{1}{8}$ ") | 6 | A47 | 11287 | Washer | 2 |
| A19 | 70/1113 | Thumb Screw | 1 | A48 | 11286 | Collar | 2 |
| A20 | A4726 | Stud | 1 | A49 | 11278 | Grubscrew | 2 |
| A21 | 70/1909 | Thumb Nut | 1 | A50 | 70/1132 | Spacer | 2 |
| A22 | 11285 | 20T Change Gear | 2 | A51 | A1644 | Change Gear Bush | 2 |
| A23 | 11285 | 25T Change Gear | 1 | A52 | 70/1107 | Change Gear Stud | 2 |
| A24 | 11285 | 30T Change Gear | 1 | A55 | 70/1115/1 | Thrust Collar | 1 |
| A25 | 11285 | 35T Change Gear | 1 | A56 | 100011 | Socket Setscrew ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") (Cup Point) | 1 |
| A26 | 11285 | 38T Change Gear | 1 | A59 | A2054/2 | Leadscrew | 1 |
| A27 | 11285 | 40T Change Gear | 1 | A60 | 70/1135/2 | R.H. Leadscrew Bracket Assembly | 1 |
| A28 | 11285 | 45T Change Gear | 1 | A62 | A8724/1 | Bed | 1 |
| A29 | 11285 | 50T Change Gear | 1 | | | | |
| A30 | 11285 | 55T Change Gear | 1 | | | | |
| A31 | 11285 | 60T Change Gear | 1 | | | | |
| A32 | 11285 | 65T Change Gear | 1 | | | | |
| A33 | 11285 | 70T Change Gear | 1 | | | | |
| A34 | 11285 | 75T Change Gear | 1 | | | | |
| A35 | 100008 | Washer ($\frac{1}{8}$ ") | 2 | | | | |
| A36 | 100032 | Hexagon Nut ($\frac{1}{8}$ " B.S.F.) | 2 | | | | |

*These parts do not apply to ML7B Quick Change Lathes.


†A12 For longbed lathe A3470

†A13 For longbed lathe 10 off

†A59 For longbed lathe A3472/1

†A62 For longbed lathe A8779/1

B




HEADSTOCK ASSEMBLY

SECTION B
HEADSTOCK ASSEMBLY

| Drg. Ref. | Part No. | Description | No. Off/Mc. | Drg. Ref. | Part No. | Description | No. Off/Mc. |
|-----------|----------|--|-------------|-----------|-----------|---|-------------|
| B1 | 65174 | Sights-feed Lubricator | 2 | B31 | 100011 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{16}$ ") (Cup Point) | 1 |
| B2 | 11261 | Fibre Washer ($\frac{1}{8}$ " B.S.P.) | 4 | B32 | 70/1206 | Spindle Bearing (Rear) | 1 set |
| B3 | 100314 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $\frac{3}{8}$ ") | 4 | B33 | 70/1204 | Laminated Shim (Rear Bearing) | 2 |
| B4 | 70/1984 | Washer | 4 | B34 | 100018 | Cheese Head Screw (2 B.A. x $\frac{1}{8}$ ") | 1 |
| B5 | 70/1202 | Bearing Cap (Rear) | 4 | B35 | 70/1242 | 20T Tumbler Gear | 1 |
| B6 | MY2820 | Grubscrew (2 B.A. x $\frac{3}{16}$ ") | 2 | B36 | 70/1241 | 18T Tumbler Gear | 1 |
| B7 | 70/1246 | 25T Gear | 1 | B37 | 100305 | Hexagon Locknut ($\frac{1}{8}$ " B.S.F.) | 2 |
| B8 | 70/1239 | Locking Collar | 1 | B38 | 70/1222 | Tumbler Reverse Stud | 1 |
| B9 | 11253 | Copper Pad | 1 | B39 | 70/1243 | Gear Stud | 2 |
| B10 | 100108 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{3}{16}$ ") (Half Dog Point) | 1 | B40 | 11287 | Washer | 1 |
| B11 | ME59/1 | Thrust Washer | 1 | B43 | 70/1208 | Tumbler Reverse Lever | 1 |
| B12 | 73044 | Thrust Bearing | 1 | B44 | 70/1219 | Plunger | 1 |
| B13 | 70/1240 | Distance Sleeve | 1 | B45 | A4728 | Spring | 2 |
| B14 | 70/1234 | Vee Cone Pulley Assembly | 1 | B46 | 70/1220 | Screwed Bush | 2 |
| B15 | 65000 | Oil Nipple (2 B.A.) | 2 | B47 | 80031 | Acorn Knob | 2 |
| B16 | 70/1227 | Backgear Key | 1 | B48 | 100405 | Socket Countersunk Screw (2 B.A. x $\frac{1}{4}$ ") | 2 |
| B17 | 70/1209 | 65T Backgear | 1 | B49 | 70/1217 | Washer | 1 |
| B18 | 100022 | Washer ($\frac{3}{16}$ ") | 1 | B50 | 70/1218 | 21/56T Backgear Cluster | 1 |
| B19 | 100023 | Cap Screw (2 B.A. x $\frac{1}{8}$ ") | 1 | B51 | A1856 | Backgear Eccentric Assembly | 1 |
| B20 | 70/1231 | Pin | 1 | B52 | 100322 | Socket Set Screw (2 B.A. x $\frac{1}{16}$ ") (Cup Point) | 2 |
| B21 | 70/1201 | Bearing Cap (Front) | 1 | B53 | 70/1207/1 | Backgear Lever | 1 |
| B22 | 70002 | Woodruff Key (No. 404) | 1 | B55 | 70020 | Vee Belt (Headstock) (23" Inside Length) | 1 |
| B23 | 70/1249 | 60" Centre (Soft) | 1 | B57 | 70/1232/1 | Tumbler Sleeve Gear | 1 |
| B24 | 70/1230 | Spindle | 1 | B58 | 100554 | Cap Screw (M8 x 1.25 x 35 mm) | 2 |
| B25 | 70/1205 | Spindle Bearing (Front) | 1 set | B59 | 100234 | Cap Screw (M8 x 1.25 x 30 mm) | 1 |
| B29 | 70/1203 | Laminated Shim (Front Bearing) | 2 | B60 | 100253 | Cap Screw (M8 x 1.25 x 25 mm) | 1 |
| B30 | 70/1228 | Pin | 2 | B61 | 70/1211/4 | Headstock | 1 |

C




CARRIAGE ASSEMBLY

SECTION C
CARRIAGE ASSEMBLY


| Dwg. Ref. | Part No. | Description | No. Off/Mc. | Dwg. Ref. | Part No. | Description | No. Off/Mc. |
|--|-----------|--|-------------|-----------|---|---|-------------|
| C1 | 70/1412 | Hexagon Nut | 1 | C31 | A7742 | Hexagon Head Bolt | 2 |
| C2 | 70/1410 | Spherical Washer | 1 | C33 | 70/1312 | Clamp Eccentric | 1 |
| C3 | 70/1409/1 | Tool Clamp | 1 | C34 | 100008 | Washer ($\frac{1}{8}$ ") | 1 |
| C4 | 70/1413 | Adjusting Screw Assembly | 1 | C35 | 1296 | Hexagon Head Bolt ($\frac{1}{8}$ " B.S.F. x $1\frac{1}{4}$ ") (Hard) | 3 |
| C5 | A2806 | Spring | 1 | C36 | 100315 | Hexagon Head Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{8}$ ") | 3 |
| C6 | 70/1406 | Tool Clamp Stud | 1 | C38 | 70/1304 | Laminated Shim (Rear) | 3 |
| C7 | 11284 | Grubscrew | 3 | C40 | 65000 | Oil Nipple (2 B.A.) | 3 |
| C8 | 70/1411 | Pin | 1 | C41 | 100316 | Round Head Screw (4 B.A. x $\frac{1}{8}$ ") | 4 |
| C9 | 70/1403 | Top Slide | 1 | C45 | 70/1305 | Laminated Shim (Front) | 2 |
| †C10 | 70/1408 | Top Slide Feedcrew | 1 | C48 | 100305 | Hexagon Locknut ($\frac{1}{8}$ " B.S.F.) | 4 |
| †C11 | 70/1401 | End Plate | 1 | C49 | 70/1319/1 | Saddle Gib Strip | 1 |
| †C12 | 100023 | Cap Screw (2 B.A. x $\frac{1}{8}$ ") | 1 | C52 | 70/1320/3 | Cross Slide Gib Strip | 1 |
| †C13 | 70/1303 | Micrometer Dial | 2 | C54 | 70/1405/2 | Top Slide Gib Strip | 1 |
| †C14 | 11293 | Top Slide Ball Handle Assembly | 1 | C55 | 11270 | Gib Strip Adjusting Screw | 2 |
| †C15 | A1845 | Tee Nut | 2 | C60 | A8736 | Wiper Housing | 1 |
| †C16 | 70/1302 | Feed Nut | 2 | C61 | A8735 | Wiper | 1 |
| †C17 | 100317 | Cheese Head Screw (4 B.A. x $\frac{1}{8}$ ") | 4 | C63 | A7760 | Adjusting Screw | 3 |
| †C19 | 11269 | Hexagon Locknut (2 B.A.) | 2 | C64 | A7424/1 | Saddle Strip (Front) | 1 |
| †C20 | 100027 | Gib Adjusting Screw | 2 | C65 | A2065 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $1\frac{1}{4}$ ") | 1 |
| †C21 | 70/1984A | Hexagon Locknut (2 B.A.) | 4 | C66 | 100313 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $1\frac{1}{4}$ ") | 1 |
| †C22 | 11257 | Washer (Hard) | 2 | C67 | 100314 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{8}$ ") | 1 |
| †C23 | 70/1321 | Fibre Washer | 2 | C68 | A2122 | Saddle Strip (Rear) | 1 |
| †C25 | 70/1321 | Cross Slide Feedcrew | 1 | C69 | 70/1308/1 | Cross Slide | 6 |
| †C26 | 70/1301 | End Plate | 1 | C70 | A8623 | Socket Setscrew (Weiglok) | 2 |
| †C27 | 70/1337 | Cross Slide Ball Handle Assembly | 1 | C71 | 100318 | Socket Setscrew (M5 x 20 mm) (Dog Point) | 2 |
| †C29 | A8079 | Top Slide Base Assembly | 1 | C72 | A8734/1 | Saddle | 1 |
| †C30 | 100005 | Washer ($\frac{1}{8}$ ") | 2 | | | | |
| † For machines having metric feedcrews with 80 and 40 division dials the following are used: | | | | | | | |
| C10 | A2282/1 | Top Slide Feedcrew Assembly | 1 | C26 | A1384 | Cross Slide End Plate | 1 |
| C11 | A1649/1 | Top Slide End Plate | 1 | C27 | A2073 | Cross Slide Ball Handle Assembly | 1 |
| C13 | A3249 | Top Slide Micrometer Dial | 1 | A2058 | Diaphragm Washer | 2 | |
| C13 | A3250/1 | Cross Slide Micrometer Dial | 1 | A1541/1 | Screw - Ball Handle Securing | 2 | |
| C14 | A2093 | Top Slide Ball Handle Assembly | 1 | A2229 | Adjusting Collar | 2 | |
| C16 | A1648 | Feed Nut (Top and Cross Slides) | 2 | A2229 | Copper Pad | 2 | |
| C25 | A2636 | Cross Slide Feedcrew Assembly | 1 | 11253 | Socket Setscrew ($\frac{1}{8}$ " B.S.F. x $\frac{3}{16}$ ") (Half Dog Point) | 2 | |

ER



TAILSTOCK ASSEMBLY

L



APRON ASSEMBLY


SECTION ER TAILSTOCK ASSEMBLY

| Part No. | Description | No. Off/Mc. |
|----------------|----------------------------------|-------------|
| ER1 A2138 | Eccentric and Lever Assembly | 1 |
| ER2 65000 | Oil Nipple (2 B.A.) | 1 |
| ER3 A2797 | Tailstock Body | 1 |
| ER4 70/1509 | Thrust Plate | 1 |
| ER5 100037 | Round Head Screw (4 B.A. x 1/2") | 1 |
| ER6 70/1520 | Handwheel Assembly | 2 |
| ER7 100038 | Rivets (No. 4 x 1/8") | 2 |
| ER8 11301 | Graduated Plate | 1 |
| ER9 A2146 | Adjusting Screw | 2 |
| ER10 A2139 | Eccentric Locating Screw | 1 |
| ER11 A2140 | Eye Bolt | 1 |
| ER12 100023 | Cap Screw (2 B.A. x 1/2") | 2 |
| ER13 A2137 | Thrust Screw | 2 |
| ER14 A2099 | Tailstock Base | 1 |
| ER15 A2136 | Gub Strip | 1 |
| ER16 70/1514 | Clamp Plate | 1 |
| ER17 100284 | 'Simmonds' Nut (1/2" B.S.F.) | 1 |
| ER21 A2798 | Barrel | 1 |
| ER22 70/1248 | 60° Centre (Hard) | 1 |
| ER23 70/1506 | Barrel Key | 1 |
| ER24 70/1507/1 | Pad Bolt and Bush | 1 |
| ER25 13355 | Stud | 1 |
| ER26 13354 | Barrel Locking Lever | 1 |

SECTION L APRON ASSEMBLY

| Part No. | Description | No. Off/Mc. |
|----------|---|-------------|
| A2086 | Hand Traverse Pinion | 1 |
| 70002 | Woodruff Key No. 404 | 1 |
| 11260 | Fibre Washer | 1 |
| A2087 | Handwheel Assembly | 1 |
| 100011 | Socket Set Screw (1/2" B.S.F. x 1/2") (Cup Point) | 1 |
| 73001 | 'Ollite' Bush (CT 15 x 1/2") | 3 |
| 100307 | Cap Screw (1/2" B.S.F. x 1/2") | 1 |
| 70/1340 | Gear Cover Assembly (Includes L8) | 1 |
| A2085 | Rack Pinion Assembly | 1 |
| A1975/2 | Leadscrew Nut | 1 |
| A4729 | Spring | 1 |
| 100319 | Cap Screw (2 B.A. x 1 1/2") | 1 |
| 100027 | Hexagon Locknut (2 B.A.) | 2 |
| A9337 | Gib Adjusting Screw | 1 |
| A2082 | Gib Strip | 2 |
| A2147 | Gib Securing Screw | 1 |
| 11295 | Stud | 1 |
| A1837/11 | Cam Lever | 1 |
| 100053 | Spring Washer | 1 |
| 100005 | Washer (1/2") | 1 |
| 100030 | 'Simmonds' Nut (1/2" B.S.F.) | 1 |
| 70/1326 | Cam Peg | 2 |
| 100320 | Hexagon Head Set Screw (2 B.A. x 1/2") | 1 |
| A9338 | Gib Adjusting Screw | 1 |
| A4188/1 | Leadscrew Guard | 1 |
| A2081/2 | Apron | 1 |
| 100257 | Cap Screw (M6 x 1 x 25 mm) | 4 |

F



MOTORISING ASSEMBLY


SECTION F

MOTORISING ASSEMBLY

| Part No. | Description | No. Off/Mc. | Part No. | Description | No. Off/Mc. |
|---------------|--|-------------|---------------|---|-------------|
| F1 100010 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") (Cup Point) ... | 2 | F26 70/1625 | Spring Clip | 1 |
| F2 A1832 | Countershaft Pulley | 1 | F27 70/1624 | Knob | 1 |
| F3 70/1628 | Countersunk Head Screw (2 B.A. x $\frac{1}{8}$ ") | 1 | F28 70025 | Vee Belt (Motor Drive) (34.5" Inside Length) ... | 1 |
| F4 100408 | Headstock Belt Guard | 3 | F29 100310 | Hexagon Head Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 1 |
| F5 70/1621/1 | Guard Retaining Plate | 2 | F30 100005 | Washer ($\frac{1}{8}$ ") | 1 |
| F6 70/1627 | Countersunk Head Screw (4 B.A. x $\frac{1}{4}$ ") | 2 | F31 A1859 | Tie Bar | 6 |
| F7 100556 | Thrust Washer | 4 | F32 A1843 | Motor Base Swing Pin | 1 |
| F8 A1973 | "Oillite" Bush | 1 | F33 70/1602/3 | Countershaft Arm | 1 |
| F9 100043 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") (Cup Point) ... | 4 | F34 70/1612 | Eccentric Shaft Collar | 1 |
| F10 70/1626/3 | Vee Cone Pulley | 2 | F35 A1862 | Tie Bar Spacer | 1 |
| F11 A1227 | Hard Rubber Bush | 1 | F36 70/1326 | Stop Peg | 1 |
| F12 65000 | Oil Nipple (2 B.A.) | 2 | F37 A4727 | Stud | 1 |
| F13 70003 | Swing Head Assembly (Includes F9) | 1 | F38 100057 | Hexagon Nut ($\frac{1}{8}$ " B.S.F.) | 4 |
| F14 70/1631/2 | Woodruff Key (No. 606) | 2 | F39 A2123 | Adjusting Screw | 2 |
| F15 70003 | Countershaft | 1 | F40 80003 | Knob ($\frac{1}{8}$ " Dia. x $\frac{1}{8}$ " B.S.W.) | 1 |
| F16 70/1619/2 | Countershaft Collar | 1 | F43 70/1604/1 | Motor Base | 1 |
| F17 MA6001 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") (Cup Point) ... | 1 | F44 100520 | Hexagon Head Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 3 |
| F18 100011 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 4 | F45 A1842 | Motor Base Swing Pin | 1 |
| F19 100313 | Countershaft Belt Guard | 1 | F46 100327 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") (Half Dog Point) | 3 |
| F20 70/1622 | Belt Guard Spacer | 1 | F47 70/1613/1 | Eccentric and Lever Assembly | 1 |
| F21 70/1983/1 | Motor Pulley ($\frac{1}{8}$ " Bore) | 1 | F48 A3969 | Swing Head Pin | 1 |
| F22 100046 | Socket Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") (Cup Point) ... | 2 | | | |
| F23 A1852/1 | Motor Pulley ($\frac{1}{8}$ " Bore) | 1 | | | |
| *F24 A1851/1 | Hexagon Head Set Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 1 | | | |
| F25 100315 | | 2 | | | |

*Standard bore size - other bores available - stated exact size required when ordering.

P



MOTORISING AND I 466 CLUTCH ASSEMBLY


SECTION P

MOTORISING AND 1466 CLUTCH ASSEMBLY

MYFORD ML7 3½" CENTRE LATHE

| Dwg. Ref. | Part No. | Description | No. Off/Mc. | Dwg. Ref. | Part No. | Description | No. Off/Mc. |
|-----------|-----------|---|-------------|---|-----------|--|-------------|
| P1 | A1936 | Pin | 1 | P53 | A1842 | Motor Base Swing Pin | 3 |
| P2 | A1795 | Adjusting Washer | 1 | P54 | 70/1326 | Stop Peg | 1 |
| P3 | 100512 | Socket Set Screw (½" B.S.F. x ½") (Cup Point) | 2 | P55 | A4727 | Stud | 1 |
| P4 | A1792 | Bush | 2 | P56 | 100057 | Hexagon Nut (½" B.S.F.) | 4 |
| P5 | A1789/1 | Countershaft Pulley | 1 | P57 | 70/1612 | Eccentric Shaft Collar | 1 |
| P6 | 65000 | Oil Nipple (2 B.A.) | 3 | P58 | A1862 | Tie Bar Spacer | 1 |
| P7 | A1953 | Sleeve Nut | 1 | P59 | 100315 | Hexagon Head Set Screw (½" B.S.F. x ½") | 2 |
| P8 | A1958 | Cam Lever Assembly (Includes P1) | 2 | P61 | 70/1624 | Knob | 1 |
| P10 | 100305 | Adjusting Screw | 1 | P62 | 70025 | Spring Clip | 1 |
| P11 | A1797 | Hexagon Locknut (½" B.S.F.) | 1 | P63 | 100310 | Vee Belt (Motor Drive) (34.5" Inside Length) | 1 |
| P12 | A1803 | Operating Rod | 4 | P64 | A1859 | Tie Bar | 1 |
| P13 | 100005 | Washer (½") | 6 | P65 | A1843 | Motor Base Swing Pin | 1 |
| P14 | A9951 | Backplate Assembly (Includes P4) | 1 | P66 | 70/1602/5 | Countershaft Arm | 1 |
| P15 | A2095 | Shim | 1 | P67 | 100313 | Cap Screw (½" B.S.F. x ½") | 1 |
| P17 | A2095 | Cover Plate | 1 | P68 | 70/1622 | Countershaft Belt Guard | 1 |
| P18 | 100406 | Countersunk Head Screw (2 B.A. x ½") | 1 | P69 | 70/1983/1 | Belt Guard Spacer | 1 |
| P19 | 70/1621/1 | Headstock Belt Guard | 1 | P70 | A1852/1 | Motor Pulley (½" Bore) | 1 |
| P20 | 70/1627 | Guard Retaining Plate | 3 | P71 | A1851/1 | Motor Pulley (½" Bore) | 1 |
| P21 | 100556 | Countersunk Head Screw (4 B.A. x ½") | 2 | P72 | 70/1613/1 | Eccentric and Lever Assembly | 1 |
| P22 | A1973 | Thrust Washer | 4 | P73 | A3969 | Swing Head Pin | 1 |
| P23 | A9943 | 'Oillite' Bush | 2 | P75 | A9950 | Countershaft Assembly (Includes P48) | 1 |
| P24 | 100043 | Socket Set Screw (½" B.S.F. x ½") (Cup Point) | 2 | P76 | A1800/1 | Actuating Shaft | 1 |
| P25 | 70/1626/3 | Vee Cone Pulley | 2 | P77 | G8003 | Washer | 1 |
| P26 | A1227 | Hard Rubber Bush | 1 | P78 | 70019 | Brake Shoe Assembly not available | 1 |
| P27 | A4732 | Swing Head Assembly (Includes P23 and P28) | 2 | * Standard bore size - other bores available - state exact size required when ordering. | | | |
| P28 | A2834/1 | 'Oillite' Bush | 1 | | | | |
| P29 | 100010 | Socket Set Screw (½" B.S.F. x ½") (Cup Point, Wedglock) | 3 | | | | |
| P30 | A1801 | Stop Pin | 2 | | | | |
| P32 | 100046 | Socket Set Screw (½" B.S.F. x ½") (Cup Point) | 2 | | | | |
| P33 | A2123 | Adjusting Screw | 2 | | | | |
| P34 | 80003 | Knob (½" Dia. x ½" Whitworth) | 2 | | | | |
| P35 | A1807 | Pivot Pin | 1 | | | | |
| P36 | 100036 | Socket Set Screw (2 B.A. x ½") (Cup Point) | 1 | | | | |
| P37 | A1805 | Lever Pivot Bracket | 1 | | | | |
| P41 | 70/1604/1 | Motor Base | 1 | | | | |
| P42 | 100520 | Hexagon Head Set Screw (½" B.S.F. x ½") | 3 | | | | |
| P43 | 100011 | Socket Set Screw (½" B.S.F. x ½") (Cup Point) | 4 | | | | |

S




20/034 TRI-LEVA SPEED SELECTOR

SECTION S

20/034 TRI-LEVA SPEED SELECTOR

MYFORD ML7 3 $\frac{1}{2}$ " CENTRE LATHE

| Dwg. Ref. | Part No. | Description | No. Off/Mc. | Dwg. Ref. | Part No. | Description | No. Off/Mc. |
|-----------|----------|--|-------------|-----------------|----------|---|-------------|
| S6 | 100005 | Washer (1") | 1 | S37 | A3496 | Stud | 1 |
| S7 | A3477/1 | Base | 1 | S38 | C1241 | Nut | 1 |
| S8 | A3478 | Belt Trap (Countershafts) | 1 | S39 | A3497 | Support Bracket | 1 |
| S9 | A3479 | Clamp (Countershaft L.H. End) | 1 | S40 | A3498 | Spherical Washer | 2 |
| S10 | 100045 | Cap Screw (4 B.A. x $\frac{1}{2}$) (N/lock) | 4 | S41 | 100083 | Hexagon Head Set Screw (1" B.S.F. x $\frac{3}{8}$) | 1 |
| S11 | A3480 | Clamp (Countershaft R.H. End) | 1 | S42 | A3514 | Rod | 1 |
| S12 | A3481 | Main Frame | 1 | S43 | A3499/1 | Slotted Cover | 1 |
| S13 | A4720A | Tensioning Arm Assembly (L.H. End) | 1 | S46 | A2023 | Pad | 3 |
| S14 | A4720B | Tensioning Arm Assembly (Centre) | 1 | S47 | A3500/1 | Lever | 3 |
| S15 | A4720C | Tensioning Arm Assembly (R.H. End) | 1 | S48 | A3502 | Adjusting Screw | 3 |
| S16 | A3483 | Pivot Pin (Lever Assembly) | 1 | S49 | A3504 | Spring | 3 |
| S17 | 100045 | Socket Set Screw (1" B.S.F. x $\frac{1}{8}$) (Cup Point) | 1 | S50 | A3505 | Pulley | 3 |
| S18 | A3484 | Collar | 1 | S51 | 73038 | Ball Bearing (RHP No. 629) | 3 |
| S19 | 100012 | Socket Set Screw (2 B.A. x $\frac{1}{16}$) (Cup Point) | 1 | S52 | A3507 | Cover | 3 |
| S20 | A3485A | Operating Arm Assembly (L.H. End) | 1 | S53 | 100405 | Socket Countersunk Screw (2 B.A. x $\frac{1}{2}$) | 3 |
| S21 | A3485B | Operating Arm Assembly (Centre) | 1 | S54 | A3781 | Retaining Ring | 3 |
| S22 | A3485C | Operating Arm Assembly (R.H. End) | 1 | S55 | 100397 | Countersunk Head Screw (4 B.A. x $\frac{1}{2}$) | 9 |
| S23 | A3486 | Radius Arm (L.H. End) | 1 | S56 | 80016 | Knob | 3 |
| S24 | A3487 | Radius Arm (R.H. End) | 1 | S57 | A3519/1 | Speed Plate | 1 |
| S25 | A3488 | Pivot Pin (Operating Arm Assembly) | 1 | S59 | A3780 | Link | 1 |
| S26 | 100036 | Socket Set Screw (2 B.A. x $\frac{1}{8}$) (Cup Point) | 2 | S60 | 100022 | Washer (1") | 2 |
| S27 | MY4402 | Copper Pad | 1 | S61 | 100546 | Cheese Head Screw (2 B.A. x $\frac{1}{2}$) | 5 |
| S28 | 100641 | Socket Set Screw (1" B.S.F. x $\frac{1}{8}$) (Half Dog Point) | 1 | S68 | 70020 | Vee Belt (23" Inside Length) | 3 |
| S29 | A3489 | Trip Plate | 1 | S69 | A3474/1 | Support Stud (Rear, L.H.) | 1 |
| S30 | A3490 | Pivot Pin (Trip Plate) | 1 | S70 | A3475/1 | Support Stud (Front, L.H.) | 1 |
| S31 | 100322 | Socket Set Screw (2 B.A. x $\frac{1}{2}$) (Cup Point) | 1 | S71 | A3476/1 | Support Stud (Front, R.H.) | 1 |
| S32 | A3491 | Stop Screw | 1 | S72 | 100071 | Hexagon Nut (M6 x 1 mm) | 6 |
| S33 | A3492 | Locknut | 2 | S73 | 100061 | Washer (M6) | 6 |
| S34 | A3493 | Hinged Cover | 1 | Not Illustrated | | | |
| S35 | A3494 | Spring | 1 | S63 | 78003 | Hexagon Key (3" A/F) | 1 |
| S36 | A3495 | Pivot Screw | 1 | S64 | 78021 | Box Spanner (1" Whit.) | 1 |
| | | | | | | Double Ended Spanner (2 B.A. x 0 B.A.) | 1 |



MYFORD QUICK CHANGE GEARBOX FOR ML7 AND SUPER 7 LATHES

NOS. 1480 (ML7) AND 1480 (SUPER 7)

MYFORD ML7 3 1/2" CENTRE LATHE

PARTS LIST FOR
QUICK CHANGE GEARBOX

| Dwg. Ref. | Part No. | Description | No. Off/Mc. | Dwg. Ref. | Part No. | Description | No. Off/Mc. |
|-----------|----------|---|-------------|-----------|----------|---|-------------|
| 131 | A2295 | Bush | 1 | 164 | A2307 | 16T Gear | 1 |
| 132 | 65015 | Sealing Washer (Dowry Selon Mark 5) | 2 | 165 | A2494 | Bush | 3 |
| 133 | 65081 | Drain Plug (1/4" B.S.F.) | 1 | 166 | 70002 | Woodruff Key (No. 404) | 1 |
| 134 | A2531 | Oil Level Plug | 1 | 167 | A3013 | 26T Gear | 1 |
| 135 | A2698 | Plug | 1 | 168 | A3014 | 52T Gear | 1 |
| 136 | A2699 | Captive Screw | 1 | 169 | A2269/1 | Selector | 1 |
| 137 | 100539 | Spring Washer (1/4" Terrys 159) | 1 | 170 | A2299 | 39T Tumbler Gear | 1 |
| 138 | 65006 | O Ring (Ref. B.S. 011) | 1 | 171 | A2296 | Spindle | 1 |
| 139 | 100370 | Cap Screw (1/4" B.S.F. x 3/8") | 1 | 172 | 100521 | Taper Pin (No. 0 x 1 1/2") | 4 |
| 140 | A3005 | Shaft | 1 | 174 | 100322 | Socket Setscrew (2 B.A. x 1/2") (Cup Point) | 1 |
| 141 | A2284 | 16T Gear | 1 | 175 | A2612 | Spring | 1 |
| 142 | 100543 | Taper Pin (No. 0 x 3/8") | 1 | 179 | A3009 | Guide Bar | 1 |
| 143 | A2304/18 | 18T Gear | 1 | 180 | A2542 | Peg End GrubscREW | 1 |
| 144 | A2304/19 | 19T Gear | 1 | 181 | 11253 | Copper Pad | 1 |
| 145 | A2304/20 | 20T Gear | 1 | 182 | 100541 | Socket Setscrew (1/4" B.S.F. x 3/8") (Half Dog Point) | 1 |
| 146 | A2304/22 | 22T Gear | 1 | 183 | A3010 | Input Shaft | 1 |
| 147 | A2301 | 24T Gear | 1 | 184 | 11286 | Collar | 1 |
| 148 | A2304/26 | 26T Gear | 1 | 185 | 100011 | Socket Setscrew (1/4" B.S.F. x 1/2") (Cup Point) | 1 |
| 149 | A2304/28 | 28T Gear | 1 | 186 | A2327 | 72T Gear | 1 |
| 150 | A2304/32 | 32T Gear | 1 | 187 | 100325 | Washer (1/4" B.S.F.) | 1 |
| 151 | A3006 | Key | 1 | 188 | 100542 | Hexagon Nut (1/4" B.S.F.) | 1 |
| 152 | A3003 | Bush | 1 | 189 | 65000 | Oil Nipple (2 B.A.) | 1 |
| 153 | A3007 | Clamping Sleeve | 1 | 191 | A3011/1 | Leadscrew | 1 |
| 154 | A2752 | Laminated Washer | 1 | 193 | A2272 | Quadrant Plate | 1 |
| 155 | A2492 | Clamp Washer | 1 | 194 | A2293 | Pivot Pin | 1 |
| 156 | 100540 | Socket Countersunk Screw (1/4" B.S.F. x 1") | 1 | 195 | 100046 | Socket Setscrew (1/4" B.S.F. x 3/8") (Cup Point) | 1 |
| 158 | 100046 | Socket Setscrew (2 B.A. x 3/8") (Cup Point) | 1 | 196 | A2286 | Thrust Block | 1 |
| 159 | A3008 | Layshaft | 1 | 197 | A2511 | Upper Lever | 1 |
| 160 | A2300 | Key | 1 | 198 | A2511 | Locating Pin | 1 |
| 161 | A2308 | 32T Gear | 1 | 199 | A2521 | Spring | 1 |
| 162 | A2605 | Oilite Bush | 1 | 200 | 11278 | GrubscREW | 1 |
| 163 | A2306 | 24T Sliding Gear | 1 | 201 | A2602/2 | Screwcutting Chart | 1 |

PARTS LIST FOR QUICK CHANGE GEARBOX (contd.)

MYFORD ML7 3 $\frac{1}{2}$ " CENTRE LATHE

| Drq. Ref. | Part No. | Description | No. Off/Mc. | Drg. Ref. | Part No. | Description | No. Off/Mc. |
|-----------|----------|---|-------------|-----------|--|---|-------------|
| 202 | A2328/1 | Change Gear Quadrant | 1 | 232 | A2754 | Drilling Template | 1 |
| 203 | A3015 | Anchor Pin | 1 | 233 | 80004 | Knob (F. W. Evans, reference No. 780) | 1 |
| 204 | 100015 | Washer ($\frac{1}{8}$ " Dia.) | 2 | 251 | 100307 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 3 |
| 205 | 100016 | Hexagon Nut ($\frac{1}{8}$ " B.S.F.) | 2 | 252 | 100462 | Cap Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 3 |
| 207 | 1000 | Hexagon Lock Nut ($\frac{1}{8}$ " B.S.F.) | 2 | 254 | A2963 | Backplate | 1 |
| 208 | A2326/1 | 19/57T Reversible Cluster Gear | 1 | 255 | 100022 | Washer ($\frac{1}{8}$ ") | 1 |
| 210 | A2325/1 | 19/57T Fixed Cluster Gear | 1 | 256 | 100326 | Hexagon Lock Nut ($\frac{1}{8}$ " B.S.F.) | 2 |
| 212 | 11287 | Washer | 1 | 258 | 70/1115/1 | Collar | 1 |
| 213 | A1999 | Retaining Screw | 1 | 259 | 65089 | Oil Nipple (Lumatic HDFV4/45) | 2 |
| 214 | A3115 | 24T Gear | 1 | 260 | A2977/2 | Top Cover | 2 |
| 216 | A2023 | Pad | 2 | 261 | 100241 | Rivet (No. 0 x $\frac{3}{8}$ ") | 8 |
| 217 | 100083 | Hexagon Head Set Screw ($\frac{1}{8}$ " B.S.F. x 1") | 2 | 262 | A2297/1 | Plunger Housing | 1 |
| 219 | 100311 | Cap Screw (2 B.A. x 1") | 1 | 264 | A2519/1 | Knob | 1 |
| 220 | A3017 | Stud | 1 | 266 | A2965/2 | Gearbox | 1 |
| 221 | 100095 | Washer ($\frac{1}{8}$ " Dia.) | 3 | 267 | 100359 | Cap Screw (M6 x 1 x 20 mm) | 2 |
| 222 | 100305 | Hexagon Lock Nut ($\frac{1}{8}$ " B.S.F.) | 2 | 268 | A2330/2 | Gear Stud | 1 |
| 223 | A2024 | Hinge Screw | 2 | 269 | A2329/3 | Gear Stud | 1 |
| 224 | A2012 | Tension Spring | 1 | 270 | A2331/1 | Link | 1 |
| 225 | 100007 | Round Head Screw (2 B.A. x $\frac{1}{8}$ ") | 3 | 271 | A2279/2 | Plunger | 1 |
| 226 | A2527/1 | Changewheel Guard (ML7) | 1 | 272 | 100132 | Circclip (1400 - 6) | 1 |
| 227 | A2528/1 | Changewheel Guard (Super 7) | 1 | | | | |
| 228 | A7934 | Metric Screwcutting Chart | 1 | | | | |
| 229 | A3018 | Spring Clip | 1 | | | | |
| | | | | N.B. | Dowels, 268 (A9287) are fitted to R.H. leadscrew bracket, A60, on quick change lathes only | | 2 |

METRIC CONVERSION SET

| | | | | | | | |
|-----|--------|--|---|-----|-------|-----------------|---|
| 139 | 100370 | Cap Head Screw ($\frac{1}{8}$ " B.S.F. x $\frac{1}{4}$ ") | 1 | 242 | 11285 | 60T Change Gear | 2 |
| 234 | A2469 | Change Gear Quadrant | 1 | 243 | 11285 | 63T Change Gear | 1 |
| 235 | A1496 | Changewheel Stud | 2 | 244 | 11285 | 50T Change Gear | 2 |
| 236 | A1501 | Sleeve | 2 | 245 | 11285 | 45T Change Gear | 2 |
| 237 | A1500 | Bush | 2 | 246 | 11285 | 28T Change Gear | 1 |
| 238 | A1498 | Washer | 2 | 247 | 11285 | 30T Change Gear | 1 |
| 239 | 100057 | Hexagon Nut ($\frac{1}{8}$ " B.S.F.) | 2 | 248 | 11285 | 35T Change Gear | 1 |
| 240 | A1499 | Changewheel Spacer | 2 | 249 | 11285 | 40T Change Gear | 1 |
| 241 | A2604 | Distance Piece | 2 | 250 | 11285 | 55T Change Gear | 1 |

GENERAL POINTS ON CENTRE LATHE PRACTICE

- (1) Clean and oil your machine after use.
- (2) When holding work in a chuck, grip as much of the material as possible. If thin flanged work is to be held, give support to the tool thrust by inserting a ring or collar between chuck body and work piece. The pressure on the jaws can be eased and so prevent straining of the chuck to avoid what is commonly known as 'Bell Mouth jaws'.
- (3) Do not grip irregular shaped material in a three-jaw chuck. Use a four-jaw chuck for rough material.
- (4) Do not swing offset jobs on the faceplate without balancing by counterweight. A piece of shaped lead clamped to the faceplate opposite the offset material will give the necessary balance to most jobs. Swinging unbalanced work places an unnecessary load on bearings and causes ovality on work being turned.
- (5) After your work has been clamped to faceplate, pull the machine round by hand and test tool and slide clearance to avoid damage by swinging bolts, etc.
- (6) When roughing out heavy stock, use the tailstock centre for support. This helps the chuck's life of accuracy and takes away some of the load applied to spindle and bearings.
- (7) When knurling, do not force knurling tool into work with too great a pressure as strain is placed upon feedscrew and nut. Use lubricating oil freely during knurling operation.
- (8) Do not leave the key in your headstock chuck. Nasty accidents occur should the lathe be switched on accidentally.
- (9) See that the spindle thrust is correctly adjusted. Any end float causes chatter.
- (10) Always wipe spindle nose and chuck register faces clean before mounting chucks, faceplates, etc.
- (11) When removing a chuck (or faceplate), do not 'yank' the chuck off with the headstock locked with the back-gear, but set the headstock for normal back-gear drive, and after placing a piece of hard wood on the lathe bed, pull the spindle round by means of the belt so that one jaw of the chuck or slot in the faceplate strikes the wood sharply. The most obstinate chuck is released in this way, and a great deal of the load is taken from the back-gear teeth.
- (12) Always clean out the spindle taper before inserting centres.
- (13) A small mark on the headstock centre with a corresponding mark on the front face of the spindle nose enables the position of location for trueness to be maintained.
- (14) Do not forget that the headstock centre (live centre) must run true and should be turned in position when correction is necessary.
- (15) Except for occasional oiling, the tailstock requires very little attention. It is, however, important that its original accuracy is maintained. The following points will assist in avoiding unnecessary tailstock troubles:—
When turning between centres, see that the barrel is as far in the tailstock body as possible. This will give greater rigidity and lessen the load on the body bore when machining. When drilling, see that the drill starts in a truly centred hole as any swing on a fairly large drill causes unnecessary wear on the sliding barrel. When turning between centres, remember that the tailstock centre has the friction of the rotating work piece to withstand and must be kept lubricated; also that when work being turned becomes heated, it expands, giving an added pressure to the contact faces. Check your work freedom at periods during the turning operation, slightly slackening the tailstock pressure when necessary. Very little trouble should arise with 'burned up' centres if these points are watched. A hardened centre when it 'burns up' needs accurate regrinding, and often the hardened particles of steel become embedded in the work being turned, causing unlimited complications unless removed.
- (16) When setting gear trains, do not mesh the change wheels too tightly.
- (17) Always remember that your ML7 Lathe is a valuable Machine Tool, and no effort should be spared to maintain its quality and accuracy.

myford

Popular Spare Parts For ML7 Lathes

History:

The ML7 lathe, was launched in August 1946, the basic bench lathe retailing at £34.00. The ML7 was so successful that it saw the immediate demise of its predecessor's, the ML2 and ML4.

The Myford "M" type, a Myford's version of the Drummond "M" type. cost £42.00 and production of this discontinued in the early 1950's.

Over it's 33 years production run the ML7 stood the test of time remarkably well. Whilst there were numerous minor changes, the number of major design changes were very few and these are listed below.

In July 1969 at serial number K90494 a cast lug was incorporated into the headstock. The lug is situated just behind the spindle nose and it's initial purpose was to act as an anchor point for the optional lever operated collet attachment. In later years the same point would be used as a pivot point for the chuck guard

In May 1972 from serial number K107657, the existing carriage was converted from the narrow guide to the wide guide principle. On the earlier machines the saddle located across the front two shears and on later models across the full width of the bed, the 5/8" diameter leadscrew and die cast apron were retained.

From lathe No. K108718 the cross slides were fitted with 5mm pitch self locking adjusting screws.

April 1973 saw the introduction of the new bed at serial number K111727, the re-design was necessary to accommodate the power cross feed apron on the Super 7 lathe. At the same time the specification of the ML7 was updated to incorporate the 3/4" diameter leadscrew and cast iron apron as used on the pre-power cross feed Super 7's.

The last machine No. K140848 left the fitting lines on the 31st January 1979.

It should be noted that long bed ML7 lathes were always fitted with a 3/4" diameter leadscrew and the saddle cross slide and top slide as used on the pre-power cross feed Super 7 lathes.

Please Note : When ordering, kindly state the serial number and prefix letter of your lathe. On earlier machines upto serial No. K111727 this will be found on the rear shear of the lathe bed, at the tailstock end of the machine. On later machines after serial number K111727 this will be found on the front of the lathe bed, to the left hand side of the rack.

SERIAL NUMBER.




Fig. 2

SERIAL NUMBER




Fig. 2.

Popular Spare Parts For ML7 Lathes

Headstock Section:

| Part Number | Description | | Price incl VAT |
|-------------|--|----------------|----------------|
| 65174 | Sight feed lubricator | £5.06 | £ 5.95 |
| 11261 | Fibre washer | £0.08 | £ 0.09 |
| 70/1230 | Spindle (Original specification) - No longer available | | - |
| 70/1205 | Spindle bearing (front) white metal - No longer available | | - |
| 70/1206 | Spindle bearing (rear) white metal - No longer available | | - |
| 70/1203 | Laminated shim - front bearing | £2.12 | £ 2.49 |
| 70/1204 | Laminated shim - rear bearing | £2.12 | £ 2.49 |
| | <p>Note: We are no longer able to purchase further supplies of the original white metal bearings at sensible prices. This has necessitated the supply of the kit detailed below as a direct replacement and in terms of cost is approximately half the price of what a new set of bearings would be.</p> | | |
| | ML7 Headstock spindle and bearing kit: | | |
| A8122 | Hardened spindle | £71.62 | £ 84.15 |
| A8120 | Spindle bearing (front) bronze, complete with shims | £55.20 | £ 64.86 |
| A8121 | Spindle bearing (rear) bronze, complete with shims | £40.13 | £ 47.15 |
| | Price for Headstock spindle with bearings complete | £166.95 | £196.16 |
| 70/1226 | 65T Backgear assembly, (including driving key etc...) | £27.10 | £ 31.85 |
| 70/1227 | Backgear key | £3.95 | £ 4.64 |
| 11163 | Special allen key, for above backgear key | £1.43 | £ 1.68 |
| 70/1218 | Backgear cluster assembly 21/56t gear | £13.26 | £ 15.58 |
| 100405 | Socket countersunk screw (2BA x 1/2") | £0.05 | £ 0.06 |
| 70/1219 | Plunger | £4.29 | £ 5.04 |
| A4728 | Spring | £0.10 | £ 0.12 |
| 70/1220 | Screwed bush | £0.15 | £ 0.18 |
| 80001 | Knob | £0.80 | £ 0.94 |
| 70/1234/2 | Vee cone pulley assembly | £42.90 | £ 50.41 |
| 70020 | Vee belt - Headstock | £5.33 | £ 6.26 |
| 65390 | Oil nipple (replaces 65000) | £0.35 | £ 0.41 |
| 73044 | Thrust bearing | £24.53 | £ 28.82 |
| 70/1246 | 25T Gear | £5.11 | £ 6.00 |
| 11260 | Grubscrew (2BA x 3/16") (MY2820) | £0.05 | £ 0.06 |
| 70/1242 | 20T Tumbler gear | £6.00 | £ 7.05 |
| 70/1241 | 18T Tumbler gear | £5.75 | £ 6.76 |
| 70/1232/2 | Tumbler sleeve gear | £16.10 | £ 18.92 |
| 70/1249 | Soft centre - 2MT | £3.70 | £ 4.35 |
| 70/1129 | 6.3/4" Standard Faceplate | £17.50 | £ 20.56 |
| 70/1137 | Catchplate with 11291 drive peg. | £15.30 | £ 17.98 |

Popular Spare Parts For ML7 Lathes

Countershaft and Motorising Section:

| Part Number | Description | Price incl VAT | |
|-------------|---|----------------|--------|
| 70/1619/2 | Countershaft | £24.08 | £28.29 |
| 70003 | Woodruff | £0.19 | £ 0.22 |
| 70/1626/6 | Vee cone pulley assembly | £20.92 | £24.58 |
| A1973 | Thrust washer | £0.07 | £ 0.08 |
| A1832 | Countershaft pulley | £12.29 | £14.44 |
| A1227 | Hard rubber bush | £3.66 | £ 4.30 |
| A2834/1 | 'Oillite' bush | £1.80 | £ 2.11 |
| 65390 | Oil nipple (replaces 65000) | £0.35 | £ 0.41 |
| 70/1624 | Knob | £3.87 | £ 4.65 |
| 70/1625 | Spring clip | £0.92 | £ 1.08 |
| 100315 | Hexagon head set screw (1/4" B.S.F. x 5/8") | £0.18 | £ 0.21 |
| 80003 | Knob (1.1/4" dia. X 5/16" B.S.W.) | £0.75 | £ 0.88 |
| A1851/1 | Motor pulley - 5/8" bore | £7.50 | £ 8.81 |
| 70025 | Vee belt - Motor drive | £3.73 | £ 4.38 |

Change Gear Train Section:

| | | | |
|-----------|--------------------------------|--------|--------|
| 70/1136/1 | Changewheel stud assembly | £12.71 | £14.93 |
| 12229 | Change gear stud | £7.00 | £ 8.23 |
| 11928 | Change gear bush | £6.05 | £ 7.11 |
| 11287 | Washer | £0.18 | £ 0.21 |
| 100018 | Cheese head screw (2BA x 3/8") | £0.05 | £ 0.06 |
| 11286 | Collar | £3.05 | £ 3.60 |
| 11278 | Grubscrew | £0.05 | £ 0.06 |
| 70/1132 | Spacer | £3.02 | £ 3.55 |
| A4736 | Change gear quadrant assembly | £9.85 | £11.57 |
| 70/1131 | Thumb screw | £3.22 | £ 3.78 |
| 70/1909/1 | Thumb nut | £2.78 | £ 3.27 |
| 65390 | Oil nipple (replaces 65000) | £0.35 | £ 0.41 |

Rack, Leadscrew and Apron Section :

| Part Number | Description | Price incl VAT | |
|-------------|---|----------------|--------|
| | Note : Diecast Apron spares for lathes with 5/8" diameter Leadscrew prior to K111727. This does not include long bed machines. | | |
| A9179 | Rack, with fixing screws - Standard bed | £25.61 | £30.09 |
| A9222 | Rack, with fixing screws - Long bed | £41.55 | £48.82 |
| A4182 | Leadscrew - 5/8" Dia. - Imperial - 8 T.P.I. - Standard bed - Changewheel machine | £79.51 | £93.42 |
| A4183 | Leadscrew - 5/8" Dia. - Imperial - 8 T.P.I. - Standard bed - Quick change gearbox machine | £79.51 | £93.42 |
| 70/1316 | Hand traverse pinion | £10.34 | £12.15 |
| 70002 | Woodruff Key (No.404) | £0.31 | £ 0.36 |
| 11258 | Fibre washer | £0.09 | £ 0.10 |
| 73074 | 'Oillite' bush (CT4 x 1.1/4") | £2.20 | £ 2.59 |
| 70/1331 | Handwheel assembly | £23.44 | £27.54 |
| 70/1315 | Rack pinion assembly | £18.19 | £21.37 |
| 11258 | Fibre washer | £0.09 | £ 0.10 |

Popular Spare Parts For ML7 Lathes

Rack, Leadscrew and Apron Section Continued:

| | | | |
|--------------|---|--------|--------|
| 73074 | 'Oilite' bush (CT4 x 1.1/4") | £2.20 | £ 2.59 |
| 73001 | 'Oilite' bush (CT15 x 1/4") | £2.10 | £ 2.47 |
| 11258 | Fibre washer | £0.09 | £ 0.10 |
| 73074 | 'Oilite' bush (CT4 x 1.1/4") | £2.20 | £ 2.59 |
| 73001 | 'Oilite' bush (CT15 x 1/4") | £2.10 | £ 2.47 |
| 70/1310/1ACC | Leadscrew nut assembly (includes 70/1326 Cam peg, A4729 Spring and 100319 2BA x 1.3/4" Cap head screw) | £11.50 | £13.51 |
| 11272 | Adjusting screw - Gib strip (MY2809) | £0.16 | £ 0.18 |
| 11271 | Adjusting screw - Gib strip (MY2806) | £0.11 | £ 0.13 |
| 100027 | Hex. Locknut (2BA) | £0.06 | £ 0.07 |
| A4188/1 | Leadscrew guard | £3.75 | £ 4.41 |
| 80003 | Knob - Cam and lever assembly | £0.75 | £ 0.88 |
| | Note : Cast Iron Apron spares for lathes with 3/4" diameter Leadscrew after K111727 and onwards. This also includes all long bed lathes. | | |
| A9179 | Rack, with fixing screws - Standard bed | £25.61 | £30.09 |
| A9222 | Rack, with fixing screws - Long bed | £41.55 | £48.82 |
| A2054/2 | Leadscrew - 3/4" Diameter - Imperial - 8 T.P.I. - Standard bed - Changewheel machine | £46.50 | £54.64 |
| A3472 | Leadscrew - 3/4" Diameter - Imperial - 8 T.P.I. - Long bed - Changewheel machine | £46.50 | £56.99 |
| A3011/1 | Leadscrew - 3/4" Diameter - Imperial - 8 T.P.I. - Standard bed - Quick change gearbox machine | £46.50 | £54.63 |
| A3839/1 | Leadscrew - 3/4" Diameter - Imperial - 8 T.P.I. - Long bed - Quick change gearbox machine | £46.50 | £56.99 |
| A2086 | Hand traverse pinion | £8.71 | £10.23 |
| 70002 | Woodruff key (No. 404) | £0.31 | £ 0.36 |
| 11260 | Fibre washer (Formerly MY4106) | £0.11 | £ 0.13 |
| A2087/1 | Handwheel assembly | £23.44 | £27.54 |
| A2085 | Rack pinion assembly | £16.68 | £19.60 |
| 11260 | Fibre washer (Formerly MY4106) | £0.11 | £ 0.13 |
| 73001 | 'Oilite' bush (CT15 x 1/4") | £2.10 | £ 2.47 |
| A1975/3ACC | Leadscrew nut assembly (includes 70/1326 Cam peg, A4729 Spring and 100319 2BA x 1.3/4" Cap head screw) | £26.09 | £30.66 |
| A9337 | Adjusting screw - Gib strip | £0.89 | £ 0.99 |
| A9338 | Adjusting screw - Gib strip | £1.23 | £ 1.44 |
| 100027 | Hexagon locknut (2BA) | £0.06 | £ 0.07 |

Saddle and Cross Slide Section:

| Part Number | Description | Price incl VAT | |
|-------------|--|----------------|--------|
| | Note : Saddle and Cross Slide - for lathes upto serial number K111727 with Diecast Apron and 5/8" diameter Leadscrew. | | |
| 70/1327 | Wiper housing | £2.82 | £ 3.31 |
| 100316 | Round head screw (4BA x 3/8") | £0.05 | £ 0.06 |
| 70/1328 | Felt wiper | £1.25 | £ 1.47 |
| 65390 | Oil nipple (replaces 65000) | £0.35 | £ 0.41 |
| 70/1305 | Laminated shim - Front | £2.20 | £ 2.59 |

Popular Spare Parts For ML7 Lathes

Saddle and Cross Slide Section Continued:

| Part Number | Description | Price incl VAT | |
|-------------|---|----------------|--------|
| 70/1304 | Laminated shim - Rear | £2.20 | £ 2.59 |
| 70/1311 | Saddle adjusting screw - Gib strip | £1.52 | £ 1.79 |
| 100027 | Hexagon locknut (2BA) | £0.06 | £ 0.07 |
| 11296 | Hexagon head bolt - Saddle clamping | £1.23 | £ 1.44 |
| 100008 | Washer (5/16") | £0.03 | £ 0.04 |
| 70/1312 | Clamp eccentric | £2.29 | £ 2.69 |
| | Note : Saddle and Cross Slide - for lathes after serial number K111727 with Cast Iron Apron and 3/4" diameter Leadscrew. | | |
| 11271 | Cross slide adjusting screw - Gib strip (MY2806) (For lathes upto serial no. K108718). | £0.11 | £ 0.13 |
| 100027 | Hexagon locknut (2BA) | £0.06 | £ 0.07 |
| A8736 | Wiper housing | £2.82 | £ 3.31 |
| 100316 | Round head screw (4BA x 3/8") | £0.05 | £ 0.06 |
| A8735 | Felt wiper | £1.25 | £ 1.47 |
| 70/1305 | Laminated shim - Front | £2.20 | £ 2.59 |
| 70/1304 | Laminated shim - Rear | £2.20 | £ 2.59 |
| A7760 | Saddle adjusting screw - Gib strip | £0.85 | £ 1.00 |
| A7424/1 | Saddle adjusting screw - Gib strip | £1.55 | £ 1.82 |
| 100305 | Hexagon locknut (1/4" B.S.F.) | £0.57 | £ 0.08 |
| 11296 | Hexagon head bolt - Saddle clamping | £1.23 | £ 1.44 |
| 100008 | Washer (5/16") | £0.03 | £ 0.04 |
| 70/1312 | Clamp eccentric | £2.29 | £ 2.69 |
| A8623 | Cross slide adjusting screw - Gib strip - For 70/1308/1 Cross slide | £0.60 | £ 0.70 |
| 100318 | Cross slide adjusting screw - Gib strip - For 70/1308/1 Cross slide | £0.20 | £ 0.23 |
| 70/1308/1 | Cross slide - Standard - No longer available - Use A1513/1 | | |
| A1513/1 | Cross slide - Long (This Cross slide is 1.7/16" longer than the standard Cross slide giving an additional tee slot) | £53.19 | £62.50 |
| 70/1301 | Cross slide end plate | £6.78 | £ 7.97 |
| 70/1321 | Feedscrew - Imperial - 10 T.P.I. - Standard cross slide | £6.41 | £ 7.53 |
| 30/133 | Feedscrew - Imperial - as above but - Fitted feednut - Std. cross slide | £10.79 | £12.68 |
| A3239 | Feedscrew - Imperial - 10 T.P.I. - Long cross Slide | £9.66 | £11.35 |
| 30/135 | Feedscrew - Imperial - as above but - Fitted feednut - Long cross slide | £13.87 | £16.30 |
| 70/1302 | Feednut - Imperial - 10 T.P.I. | £4.95 | £ 5.81 |
| A4730 | Feedscrew - Metric - 2mm Pitch - Standard cross slide | £6.41 | £ 7.53 |
| 30/134 | Feedscrew - Metric - as above but - Fitted feednut - Std cross slide | £10.79 | £12.68 |
| A7822 | Feedscrew - Metric - 2mm Pitch - Long cross Slide | £9.66 | £11.35 |
| 30/136 | Feedscrew - Metric - as above but - Fitted feednut - Long cross slide | £13.87 | £16.30 |
| A1648 | Feednut - Metric - 2mm Pitch | £4.95 | £ 5.81 |
| 70/1984A | Hard washer | £0.12 | £ 0.14 |
| 11257 | Fibre washer | £0.08 | £ 0.09 |
| 11107 | Steel micrometer dial (replaces 70/1303 Mazak dial) | £7.00 | £8.23 |
| | or | | |
| 20/252 | Re-settable micrometer dial | £10.65 | £12.51 |
| A1382/3 | Gib strip | £4.00 | £ 4.70 |
| 70/1337 | Ball handle assembly | £10.10 | £11.87 |
| A8623 | Cross slide adjusting screw - Gib strip | £0.60 | £ 0.70 |
| 100318 | Cross slide locking screw | £0.25 | £ 0.29 |
| | Note : For long bed ML7 lathes, refer to Super 7 spares list pages 5 and 6. | | |

Popular Spare Parts For ML7 Lathes

Top Slide Section :

| Part Number | Description | | Price incl VAT |
|-------------|---|---------|----------------|
| 11292 | Top slide assembly complete - Imperial | £131.78 | £154.84 |
| 13726 | Top slide assembly complete - Metric | £131.78 | £154.84 |
| 70/1403 | Top slide | £20.42 | £ 23.99 |
| 70/1401 | End plate | £5.30 | £ 6.22 |
| 70/1408 | Feedscrew - Imperial - 10 T.P.I. | £6.70 | £ 7.87 |
| 30/137 | Feedscrew - Imperial - as above but - Fitted feednut | £11.06 | £ 12.30 |
| 70/1302 | Feednut - Imperial - 10 T.P.I. | £4.95 | £ 5.81 |
| A4731 | Feedscrew - Metric - 2mm Pitch | £6.70 | £ 7.87 |
| 30/138 | Feedscrew - Metric - 2mm Pitch - as above but - Fitted feednut | £11.06 | £ 12.30 |
| A1648 | Feednut - Metric - 2mm Pitch | £4.95 | £ 5.81 |
| 70/1984A | Hard washer | £0.12 | £ 0.14 |
| 11257 | Fibre washer | £0.08 | £ 0.09 |
| 11107 | Steel micrometer dial (replaces 70/1303 Mazak dial) | £7.00 | £ 8.23 |
| | or | | |
| 20/252 | Re-settable micrometer dial | £10.65 | £ 12.51 |
| 11293 | Ball handle assembly | £8.12 | £ 9.54 |
| 11269 | Adjusting screw - Gib strip | £0.25 | £ 0.29 |
| 100027 | Hexagon locknut (2BA) | £0.06 | £ 0.07 |
| 70/1406 | Tool clamp stud | £5.42 | £ 6.37 |
| A2806 | Spring | £0.27 | £ 0.32 |
| 70/1409/1 | Tool clamp | £4.61 | £ 5.42 |
| 70/1413 | Adjusting screw assembly | £4.03 | £ 4.74 |
| 70/1410 | Spherical washer | £1.25 | £ 1.47 |
| 70/1412 | Tool clamp locking nut | £0.62 | £ 0.73 |
| A1845 | Tee nut, complete with A7742 hex headed bolt and washer (Two required per machine) | £2.96 | £ 3.48 |
| | Note : For long bed ML7 lathes, refer to Super 7 spares list pages 7 and 8. | | |

Tailstock Section :

| | | | |
|-----------|-----------------------------|---------|---------|
| 13356 | Tailstock assembly complete | £216.75 | £254.68 |
| A2798 | Barrel | £29.61 | £ 34.79 |
| 70/1506 | Barrel key | £2.06 | £ 2.42 |
| 70/1520/1 | Handwheel assembly | £36.23 | £ 42.57 |
| 70/1509 | Thrust plate | £7.89 | £ 9.27 |
| 70/1248 | Hard centre - 2 M.T. | £5.35 | £ 6.28 |
| A2137 | Thrust screw - Gib strip | £5.31 | £ 6.24 |
| A2146 | Set over screw | £0.59 | £ 0.69 |
| 65390 | Oil nipple (replaces 65000) | £0.35 | £ 0.41 |

Popular Spare Parts For ML7 Lathes

Plates :

| | | | |
|-------|-----------------------------------|-------|--------|
| A2639 | Screw cutting chart | £2.05 | £ 2.41 |
| | Transfer for headstock belt guard | £0.42 | £ 0.50 |

Sundries :

| Part Number | Description | Price incl VAT | |
|-------------|--|----------------|--------|
| 33/038 | Paint - Grey - 250ml tin (Air drying enamel) | £4.20 | £ 4.94 |
| 80163 | Castrol Moly grease - 400gm. tub - ideal for changewheels, feedscrew and leadscrews. | £3.02 | £ 3.55 |
| 80024 | Lubricating oil - H32 Nuto - 1 Ltr. For headstock spindle, tailstock barrel and oilite bushes. | £3.80 | £ 4.47 |
| 80025 | Lubricating oil - Febis K68 - 1 Ltr. For bed, slideways and gearbox. | £3.80 | £ 4.47 |
| | Installation and maintenance manuals (Nil V.A.T. on manuals) | | |
| 82005 | ML7 | £4.45 | - |
| 82006 | Quick change gearbox | £1.70 | - |

Extra Equipment :

| Part Number | Description | Price incl VAT | |
|-------------|---|----------------|---------|
| 1480 | Quick change gearbox | £531.50 | £624.51 |
| 1440A | Lever operated tailstock attachment | £78.50 | £ 92.24 |
| 30/021A | Chuck guard for machines before lathe Serial No. K.91000 | £60.40 | £ 70.97 |
| 30/021 | Chuck guard for machines after lathe Serial No. K.91000 | £37.32 | £ 48.85 |
| 30/027 | Chuck guard Kit to meet requirements of health and Safety at work etc. Act, 1974, comprising: primary drive guard backplate, guard for rear end of headstock spindle and guard for swing head, including No. 30/021 chuck guard (please state serial number of machine) for machines after lathe Serial No. K.91000 | £84.64 | £ 99.45 |
| A1781 | 18T Tufnol pinion for tumbler reverse | £5.75 | £ 6.75 |
| A1782 | 20T Tufnol pinion for tumbler reverse | £5.95 | £ 6.99 |
| A1974/1 | Fine feed tumbler cluster gear | £12.50 | £ 14.68 |
| 11574 | Lathe cover | £14.60 | £ 17.15 |
| 11575 | Lathe cover for long bed lathe | £16.00 | £ 18.80 |

Copyright (C) 1997 Myford Ltd.

Published by Myford Ltd. Printed in Great Britain

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without the prior written permission of the publishers.
Illustrations not binding in detail. Design and specification subject to change without notice.

Myford Limited,
Wilmot Lane, Chilwell Road,
Beeston, Nottingham,
England, NG9 1ER.

Tel: (0115) 9254222. Fax: (0115) 9431299